

```
body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals { page-break-inside: avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; } #doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button, #doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border: none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding: 10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; } body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf } body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; } body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; } jQuery(document).ready(function() { jQuery("#invoice.sa_invoice-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("#estimate.sa_estimate-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href", "https://valleywidepro.com/estimate/6e3ea09884eeb72b47a104ba1f9cd596/"); jQuery(".button.primary_button.purchase_button").attr("href", "https://valleywidepro.com/estimate/6e3ea09884eeb72b47a104ba1f9cd596/"); jQuery(".button.primary_button.payment_option").attr("href", "https://valleywidepro.com/estimate/6e3ea09884eeb72b47a104ba1f9cd596/"); jQuery("#change_payment_amount").attr("href", "https://valleywidepro.com/estimate/6e3ea09884eeb72b47a104ba1f9cd596/"); });
```

(13100) FOAM MAINT. – 9233 E Sun Lakes South

Print to PDF

Accepted

Decline Estimate

Henry Diaz

9233 E Sun Lakes South
Sun Lakes, AZ 85248
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US

Date

March 17, 2026

Estimate Number

13100

Estimate Due

April 16, 2026

Estimate Total

\$0.00

Service

Price

Amount

- This maintenance applies to the entire foam roof at **38 sq's.**

\$8,400

\$8,400

- Power wash entire flat roof and clean roof free of debris.
- Repair under A/C unit
- Install two layers of 1.5 gallons per square of elastomeric coating.
- 8 Year Workmanship Warranty

	Subtotal	\$0.00
--	-----------------	--------

	Total	\$0.00
--	--------------	--------

Thank you; we really appreciate your business! Let us know if you have any questions about your estimate.

To approve this estimate, 50% is due prior to the beginning of the project. 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Phone: (877) 692-9762

Email: info@azroc.gov

Address: Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812

Website: www.azroc.gov

Please reference our license number ROC# 348219 when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

To approve this estimate, 50% is due prior to the beginning of the project.

<https://valleywidepro.com> billing@valleywidepro.com



Estimate updated by valleywide.

 Updated

March 17, 2026 @ 8:48 am

Estimate viewed by (valleywide) for the first time.

 Viewed

March 17, 2026 @ 8:48 am

 Viewed

March 17, 2026 @ 8:48 am

Estimate viewed by for the first time.

 Viewed

March 17, 2026 @ 9:03 am

Estimate viewed by 104.23.195.87 for the first time.

 Viewed

March 17, 2026 @ 9:14 am

Estimate viewed by 104.22.17.165 for the first time.

 Viewed

March 17, 2026 @ 8:12 pm

Estimate viewed by 172.69.74.252 for the first time.

 Viewed

March 18, 2026 @ 2:09 am

Estimate viewed by 104.22.62.12 for the first time.

 Viewed

March 19, 2026 @ 4:10 pm

Estimate viewed by 104.23.195.86 for the first time.

 Viewed

March 19, 2026 @ 4:23 pm

Estimate viewed by 172.69.134.83 for the first time.

 Viewed

March 23, 2026 @ 7:38 pm

Estimate viewed by 172.69.74.253 for the first time.

 Viewed

March 25, 2026 @ 7:21 pm

Estimate viewed by 172.69.7.16 for the first time.

 Viewed

March 26, 2026 @ 10:30 am

Estimate viewed by 172.69.22.174 for the first time.

 Viewed

March 31, 2026 @ 7:50 am

Estimate viewed by 104.22.20.114 for the first time.

 Viewed

April 30, 2026 @ 8:35 am

Estimate viewed by 172.71.158.42 for the first time.

 Status Update

April 30, 2026 @ 10:52 am

Status changed: Pending to **Approved**.

 Updated

April 30, 2026 @ 10:57 am

Estimate updated by valleywide.

 Updated

April 30, 2026 @ 10:57 am

Estimate updated by valleywide.

 Updated

April 30, 2026 @ 11:00 am

Estimate updated by valleywide.

 Updated

April 30, 2026 @ 11:00 am

Estimate updated by valleywide.

 Viewed

April 30, 2026 @ 11:10 am

Estimate viewed by 172.70.126.102 for the first time.

 Status Update

April 30, 2026 @ 11:10 am

Status changed: Approved to **Pending**.

 Updated

April 30, 2026 @ 11:10 am

Estimate updated by valleywide.

 Updated

April 30, 2026 @ 11:10 am

Estimate updated by valleywide.

 Status Update

April 30, 2026 @ 11:14 am

Status changed: Pending to **Approved**.

 Viewed

April 30, 2026 @ 11:40 am

Estimate viewed by 172.70.179.88 for the first time.



