

```
var signObjects = new Array('ctISignature'); var objctISignature = new SuperSignature({SignObject:'ctISignature',SignWidth:
"450",TransparentSign:"true",SignHeight: "300",leModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor: "#FFFFFF",
BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-pro/bundles/sprout-
invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-pro/bundles/sprout-
invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.", ErrorMessage: "Please continue with a valid
signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.", SignzIndex: 1000, Visible: "true", forceMouseEvent: true,
Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctISignature.Init(); $('#sign_doc').on('click', function(event) {
event.preventDefault(); // scroll to signature $('html, body).animate({ scrollTop: $('#ctISignature_Container').offset().top + 1000});
$('#save_signature_via_ajax').on('click', function(event) { if (! ValidateSignature() ) { return; } var sig_data = $('#ctISignature_data').val(),
sig_data_smooth = $('#ctISignature_data_canvas').val(); $(this).after(si_js_object.inline_spinner); $.post( si_js_object.ajax_url, { action:
'si_save_signature', invoice_id: 14512, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce: si_js_object.security }, function( response ) {
$('.spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $('#sign_doc').hide(); $('#ctISignature_toolbar').hide(); // show signature
$('#si_signature_wrap').html( response.data.img ); // Add ability to pay $(' .stipe_checkout_button' ).show(); $(' .square_checkout' ).show(); $('
.button.status_change' ).show(); $(' .a.button.primary_button.purchase_button' ).show(); $(' .a.button.primary_button.payment_option' ).show(); // New
Theme $('#paybar .inner .button.open').show(); // scroll to the top $('html, body).animate({ scrollTop: $('#outer_doc_wrap').offset().top }, 500); } else {
$('#save_signature_via_ajax').after(" + response.data.message + " ); } } ); //]]> body { background-color: transparent; } img, p, li, .line_item,
.si_default_theme .item, #line_items_footer, #footer_wrap, #totals { page-break-inside:avoid } #paybar { position: static !important; }
#outer_doc_wrap { margin: 0 10px 10px 10px; } #doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important;
border: none; } #print_to_pdf_button, #doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display:
none; } #document_wrap { border: none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; }
body.si_default_theme #header .inner { padding: 10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default {
background-color: #fff; color: #333; } body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes
.item .header h3 { color: #afafaf } body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme
#notes .item .header h3 { border-color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header {
background-color: #f7f7f7; } body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner {
display: none; } jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass( 'clearfix' ).addClass(
'newcf' ); jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass( 'clearfix' ).addClass( 'newcf' );
jQuery("a[href='#payment']").attr("href", "https://valleywidepro.com/estimate/9ebd28ef97c8b69ef27192ca11d3819c/");
jQuery(".button.primary_button.purchase_button").attr("href", "https://valleywidepro.com/estimate/9ebd28ef97c8b69ef27192ca11d3819c/");
jQuery(".button.primary_button.payment_option").attr("href", "https://valleywidepro.com/estimate/9ebd28ef97c8b69ef27192ca11d3819c/");
jQuery("#change_payment_amount").attr("href", "https://valleywidepro.com/estimate/9ebd28ef97c8b69ef27192ca11d3819c/"); } );
```

14512

.button.status_change, a.button.primary_button.purchase_button, a.button.primary_button.payment_option { display: none; } .stipe_checkout_button { display: none; } .square_checkout { display: none; } .button.status_change[data-status-change='decline'] { display: inline-block !important; }

[Decline Estimate](#)

[Signature Required](#) [Print to PDF](#) [Accept Estimate](#)

Richard Dyer (34th Way)
13223 S 34TH WAY
PHOENIX, AZ 85044
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US

Date


Estimate Number

Estimate Due

May 5, 2026

14512

June 4, 2026

 **Estimate Total**
\$23,100.00

Attachments



13223 South 34th Way, Phoenix, Arizona, United States

Service	Price	Amount
<ul style="list-style-type: none"> • This applies to installing a new foam roof over the entire flat roof @ 45 sq's & 10 sq's parapet walls • Remove existing roofing system from the entire flat roof • Remove and replace (5) plywood sheets as needed through the roof. Additional plywood sheets as needed would add \$80/sheet to the total. • Apply 1" foam over the entire flat roof. • Remove and replace T-Tops from the foam roof. • Seal all penetrations, haul away debris, and keep yard clean. • Provide 10-year warranty against leaks over the entire new foam roof, @ 45 sq's <p>WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed in the TOTAL.</p> <p>50% due at signing / 50% due upon completion.</p>	\$23,100	\$23,100
	Subtotal	\$0.00
	Total	\$23,100.00

To approve this estimate, 50% is due at signing, 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Phone: (877) 692-9762

Email: info@azroc.gov

Address: Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812

Website: www.azroc.gov

Please reference our license number ROC# 348219 when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

Thank you; we really appreciate your business! Please be sure to leave us a review upon completion of your project. Referrals are our lifeline, please tell your neighbors about Valleywide Pro Roofing!

Save Signature!

<https://valleywidepro.com> billing@valleywidepro.com



 Viewed
May 5, 2026 @ 10:46 pm

Estimate viewed by for the first time.

 Viewed
May 5, 2026 @ 10:47 pm

Estimate viewed by 172.69.7.16 for the first time.

Estimate viewed by 172.71.255.2 for the first time.

 Viewed

May 5, 2026 @ 10:47 pm

 Viewed

May 9, 2026 @ 11:33 am



Estimate viewed by 172.71.254.254 for the first time.