

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:'ctlSignature',SignWidth:
"450",TransparentSign:"true",SignHeight:"300",IsModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor: "#FFFFFF",
BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-pro/bundles/sprout-
invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-pro/bundles/sprout-
invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.", ErrorMessage: "Please continue with a valid
signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.", SignIndex: 1000, Visible: "true", forceMouseEvent: true,
Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init(); $('#sign_doc').on('click', function(event) {
event.preventDefault(); // scroll to signature $('html, body').animate({ scrollTop: $('#ctlSignature_Container').offset().top + 1000}); });
$('#save_signature_via_ajax').on('click', function(event) { if (! ValidateSignature() ) { return; } var sig_data = $('#ctlSignature_data').val(),
sig_data_smooth = $('#ctlSignature_data_canvas').val(); $(this).after(si_js_object.inline_spinner); $.post( si_js_object.ajax_url, { action:
'si_save_signature', invoice_id: 3880, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce: si_js_object.security }, function( response ) {
$('.spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $('#sign_doc').hide(); $('#ctlSignature_toolbar').hide(); // show signature
$('#si_signature_wrap').html( response.data.img ); // Add ability to pay $(' .stipe_checkout_button' ).show(); $(' .square_checkout' ).show(); $('
.button.status_change' ).show(); $(' a.button.primary_button.purchase_button' ).show(); $(' a.button.primary_button.payment_option' ).show(); // New
Theme $('#paybar .inner .button.open').show(); // scroll to the top $('html, body').animate({ scrollTop: $('#outer_doc_wrap').offset().top }, 500); } else {
$('#save_signature_via_ajax').after(" + response.data.message + " ); }); }); //]]> body { background-color: transparent; } img, p, li, .line_item,
.si_default_theme .item, #line_items_footer, #footer_wrap, #totals { page-break-inside:avoid } #paybar { position: static !important; }
#outer_doc_wrap { margin: 0 10px 10px 10px; } #doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important;
border: none; } #print_to_pdf_button, #doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display:
none; } #document_wrap { border: none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; }
body.si_default_theme #header .inner { padding: 10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default {
background-color: #fff; color: #333; } body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes
.item .header h3 { color: #afafaf } body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme
#notes .item .header h3 { border-color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header {
background-color: #f7f7f7; } body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner {
display: none; } jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass( 'clearfix' ).addClass(
'newcf' ); jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass( 'clearfix' ).addClass( 'newcf' );
jQuery("a[href='#payment']").attr("href", "https://valleywidepro.com/estimate/ad620356cd4c0f1ab6e44481d0be039a/");
jQuery(".button.primary_button.purchase_button").attr("href", "https://valleywidepro.com/estimate/ad620356cd4c0f1ab6e44481d0be039a/");
jQuery(".button.primary_button.payment_option").attr("href", "https://valleywidepro.com/estimate/ad620356cd4c0f1ab6e44481d0be039a/");
jQuery("#change_payment_amount").attr("href", "https://valleywidepro.com/estimate/ad620356cd4c0f1ab6e44481d0be039a/"); });
```

## (3880) Tile Replace – 3535 N 143RD LN (Alfredo Beas)

.button.status\_change, a.button.primary\_button.purchase\_button, a.button.primary\_button.payment\_option { display: none; } .stipe\_checkout\_button { display: none; } .square\_checkout { display: none; } button.status\_change[data-status-change='decline'] { display: inline-block !important; }

[Decline Estimate](#)

[Signature Required](#) [Print to PDF](#) [Accept Estimate](#)

Beas Homes

US



Valleywide Pro Roofing 4022 W  
Palo Verde Dr  
Phoenix, AZ 85019  
US

Date

Estimate Number

Estimate Due


 Estimate Total

\$1.00

## Attachments



3535-North-143rd-Lane-Goodyear-AZ-85395

Service	Price	% 	Amount
<p><b>ESTIMATE SPECS FOR TILE ROOF REPLACE</b></p> <ul style="list-style-type: none"> <li>—This proposal applies to the entire Tile Roof @ <b>29</b> sq's.</li> <li>—Remove tile then set aside, re-install after repair (unless broken—then replace).</li> <li>—Remove felt and remove and replace battens from the entire roof.</li> <li>—Remove and replace any sheets of bad plywood (as needed) throughout the roof. <i>Additional plywood billed at \$80/sheet.</i></li> <li>—Install new SBS rolled roofing as needed.</li> <li>—Install new <b>[SEE OPTIONS BELOW]</b> underlayment over the entire roof.</li> <li>—Install new 3 inch x 3 inch drip edge around the perimeter of the entire roof.</li> <li>—Install new 3 ribbed valley metals, and channel metals as needed throughout the ROOF.</li> <li>—Install new L metals, roof jacks, T-Top air vents, and O'Haggin vents throughout the roof as needed. (proper ventilation)</li> <li>—Install all new Fascia Board as needed</li> <li>—Install new ridge and hip enclosures as needed throughout the roof</li> <li>—Install new bird stops as needed throughout the tile roof</li> <li>—Seal all penetrations, haul away debris and keep yard clean.</li> <li>—Provide <b>[SEE BELOW]</b> limited warranty against leaks over the entire Tile roof, @ 29 sq's.</li> </ul> <p>ESTIMATED COMPLETION: <b>2-3</b> Days</p> <p><b>WE PROPOSE</b> hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed below. Tax is included in price:</p> <p><b>GOOD (SINGLE-LAYER UNDERLAYMENT): \$10,800 – 10 YEAR LIMITED WARRANTY*</b></p> <p><b>BETTER (DOUBLE-LAYER UNDERLAYMENT): \$11,700 – 15 YEAR LIMITED WARRANTY*</b></p> <p><b>BEST (TILE-SEAL): \$13,200 – 30 YEAR LIMITED WARRANTY*</b></p>	\$1	0%	\$1

\*See warranty statement below.

	Subtotal	\$0.00
	Total	\$1.00

Thank you; we really appreciate your business! Let us know if you have any questions about your estimate.

**Please see attachments for full roof report information.**

50% is due prior to the beginning of the project. 50% due upon completion.

#### Customer Satisfaction Statement

At Valleywide Pro Roofing, LLC, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

**Phone:** (877) 692-9762

**Email:** [info@azroc.gov](mailto:info@azroc.gov)

**Address:** Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812

**Website:** [www.azroc.gov](http://www.azroc.gov)

Please reference our license number [ROC# 348219](#) when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

---

### Warranty Statement for Roof Replacement Options

Thank you for choosing Valleywide Pro Roofing, LLC for your roofing needs. We are committed to providing high-quality materials and professional installation to ensure the longevity and performance of your new roof. To maximize the lifespan of your roof and maintain warranty coverage, the following warranty terms and conditions apply:

#### 1. Warranty Coverage

All roof replacement options come with a comprehensive warranty that includes:

**Underlayment Warranty:** Coverage as per the manufacturer's warranty, ranging from 10 to 50 years depending on the underlayment type selected.

**Tile Warranty:** Coverage as per the manufacturer's warranty, ranging from 30 years to a lifetime, depending on the type of tile selected (standard concrete, premium concrete, or clay tiles).

#### 2. Maintenance Requirements

To maintain the validity of the warranty beyond the initial 10 years, an **annual maintenance package** is required. This package is designed to ensure your roof remains in optimal condition and any potential issues are addressed promptly.

**Annual Maintenance Package Cost:** \$299/year.

**Discounted Maintenance Plan:** Customers have the option to pre-pay for maintenance in 5-year bundles at a discounted rate. See below for discounts.

Discounted Rates:

**5-Year Maintenance Bundle:** \$1,345 (a savings of \$150 compared to annual payments).

### 3. Manufacturer Warranty Claims

While Valleywide Pro Roofing, LLC provides a workmanship warranty on the installation and materials used, any claims related to the manufacturer's warranties (underlayment and tiles) must be processed directly through the manufacturer. Our team is available to assist you in facilitating these claims to ensure a smooth and efficient process.

### 4. Terms and Conditions

**Warranty Activation:** The warranty will become effective on the date of completion of the roof installation.

**Maintenance Schedule:** The annual maintenance package is mandatory after the initial 5-year period to continue the coverage. Failure to comply with the annual maintenance schedule may void the warranty.

**Coverage Exclusions:** The warranty does not cover damage caused by natural disasters, improper use, or modifications made to the roof after installation without prior consultation with Valleywide Pro Roofing, LLC. The warranty does not cover any work performed by other roofing contractors or companies not associated with Valleywide Pro Roofing, LLC.

**Warranty Transfer:** The warranty is transferable to a new homeowner upon the sale of the property, provided that all maintenance requirements have been met. A **one-time transfer fee of \$250** is required to transfer the warranty to the new homeowner.

We appreciate your business and are dedicated to providing you with a roof that offers protection and peace of mind for years to come. If you have any questions regarding the warranty or maintenance packages, please do not hesitate to contact us.

**Save Signature!**



-  **Status Update**  
November 4, 2024 @ 12:48 am  
Status changed: Draft to Pending.
-  **Viewed**  
November 4, 2024 @ 12:48 am  
Estimate viewed by 172.69.6.79 for the first time.
-  **Viewed**  
November 4, 2024 @ 12:48 am  
Estimate viewed by 172.69.6.59 for the first time.
-  **Viewed**  
November 4, 2024 @ 1:14 am  
Estimate viewed by (valleywide) for the first time.
-  **Viewed**  
November 4, 2024 @ 1:16 am  
Estimate viewed by 172.69.6.214 for the first time.
-  **Viewed**  
November 4, 2024 @ 1:18 am  
Estimate viewed by for the first time.
-  **Viewed**  
November 4, 2024 @ 12:53 pm  
Estimate viewed by 172.70.206.183 for the first time.
-  **Viewed**  
December 16, 2024 @ 2:41 pm  
Estimate viewed by 172.68.118.54 for the first time.
-  **Viewed**  
February 11, 2025 @ 12:14 am  
Estimate viewed by 172.70.100.59 for the first time.
-  **Viewed**  
February 14, 2025 @ 2:42 am  
Estimate viewed by 172.69.17.13 for the first time.
-  **Viewed**  
February 23, 2025 @ 1:29 pm  
Estimate viewed by 172.70.130.18 for the first time.

 **Viewed**  
March 1, 2025 @ 5:59 pm

Estimate viewed by 162.158.189.102 for the first time.

 **Viewed**  
March 10, 2025 @ 1:59 pm

Estimate viewed by 172.71.219.84 for the first time.

 **Viewed**  
March 16, 2025 @ 4:29 pm

Estimate viewed by 172.71.81.12 for the first time.

 **Viewed**  
April 13, 2025 @ 10:00 pm

Estimate viewed by 172.68.118.245 for the first time.

 **Viewed**  
May 9, 2025 @ 12:37 am

Estimate viewed by 172.71.1182 for the first time.

 **Viewed**  
June 3, 2025 @ 12:55 pm

Estimate viewed by 172.68.26.245 for the first time.

 **Viewed**  
June 3, 2025 @ 2:03 pm

Estimate viewed by 172.68.26.191 for the first time.

 **Viewed**  
June 4, 2025 @ 9:39 pm

Estimate viewed by 172.69.6.121 for the first time.

 **Viewed**  
June 5, 2025 @ 3:13 am

Estimate viewed by 172.70.100.84 for the first time.

 **Viewed**  
June 5, 2025 @ 4:43 pm

Estimate viewed by 172.69.17.66 for the first time.

 **Viewed**  
June 7, 2025 @ 10:43 pm

Estimate viewed by 172.71.166.106 for the first time.

 **Viewed**  
June 30, 2025 @ 2:42 am

Estimate viewed by 172.70.114.241 for the first time.

 Viewed  
July 1, 2025 @ 12:15 pm

Estimate viewed by 172.70.194.132 for the first time.

 Viewed  
July 31, 2025 @ 6:13 am

Estimate viewed by 172.70.91.84 for the first time.

 Viewed  
September 5, 2025 @ 1:46 am

Estimate viewed by 162.158.94.96 for the first time.

 Viewed  
September 5, 2025 @ 8:52 am

Estimate viewed by 162.158.155.158 for the first time.

 Viewed  
September 5, 2025 @ 1:34 pm

Estimate viewed by 172.71.215.200 for the first time.

 Viewed  
September 9, 2025 @ 10:58 am

Estimate viewed by 172.71.146.229 for the first time.

 Viewed  
September 12, 2025 @ 2:52 am

Estimate viewed by 108.162.216.194 for the first time.

 Viewed  
September 18, 2025 @ 9:45 pm

Estimate viewed by 172.70.131.135 for the first time.

 Viewed  
October 30, 2025 @ 2:22 am

Estimate viewed by 172.69.7.44 for the first time.

 Viewed  
November 22, 2025 @ 5:37 am

Estimate viewed by 104.23.213.80 for the first time.

 Viewed  
December 16, 2025 @ 3:35 pm

Estimate viewed by 172.71.82.29 for the first time.

 Viewed  
December 31, 2025 @ 6:41 am

Estimate viewed by 104.23.211.90 for the first time.

 Viewed  
February 3, 2026 @ 10:17 pm

Estimate viewed by 172.71.195.89 for the first time.

 Viewed  
February 6, 2026 @ 3:13 am

Estimate viewed by 104.23.239.144 for the first time.

 Viewed  
March 4, 2026 @ 8:37 am

Estimate viewed by 172.69.7.15 for the first time.

 Viewed  
March 19, 2026 @ 7:01 pm

Estimate viewed by 198.41.227.18 for the first time.

 Viewed  
April 14, 2026 @ 9:12 am

Estimate viewed by 172.70.144.36 for the first time.

 Viewed  
April 14, 2026 @ 9:12 am

Estimate viewed by 172.70.94.48 for the first time.

 Viewed  
April 17, 2026 @ 10:41 pm

Estimate viewed by 104.23.211.91 for the first time.

 Viewed  
April 24, 2026 @ 6:09 pm


Estimate viewed by 172.71.155.172 for the first time.

 Viewed  
April 27, 2026 @ 5:24 am

Estimate viewed by 172.69.59.156 for the first time.

 Viewed  
April 27, 2026 @ 5:24 am

Estimate viewed by 172.69.17.139 for the first time.

 Viewed  
April 29, 2026 @ 8:44 am

Estimate viewed by 172.69.155.222 for the first time.

