

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:"ctlSignature",SignWidth:
"450",TransparentSign:"true",SignHeight:"300",IsModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor:
"#FFFFFF", BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-
pro/bundles/sprout-invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-
invoices-pro/bundles/sprout-invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.",
ErrorMessage: "Please continue with a valid signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.",
SignzIndex: 1000, Visible: "true", forceMouseEvent: true, Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init();
$("#sign_doc").on('click', function(event) { event.preventDefault(); // scroll to signature $('html, body').animate({ scrollTop:
$("#ctlSignature_Container").offset().top }, 1000); }); $("#save_signature_via_ajax").on('click', function(event) { if ( ! ValidateSignature() ) { return; }
var sig_data = $("#ctlSignature_data").val(), sig_data_smooth = $("#ctlSignature_data_canvas").val(); $(this).after(si_js_object.inline_spinner);
$.post( si_js_object.ajax_url, { action: 'si_save_signature', invoice_id: 6216, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce:
si_js_object.security }, function( response ) { $('spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $('#sign_doc').hide();
$("#ctlSignature_toolbar").hide(); // show signature $('#si_signature_wrap').html( response.data.img ); // Add ability to pay $(
'stipe_checkout_button').show(); $('.square_checkout').show(); $('.button.status_change').show(); $('a.button.primary_button.purchase_button'
).show(); $('a.button.primary_button.payment_option').show(); // New Theme $('#paybar_inner.button.open').show(); // scroll to the top $('html,
body').animate({ scrollTop: $("#outer_doc_wrap").offset().top }, 500); } else { $("#save_signature_via_ajax").after(" + response.data.message + "); }
}); //> body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals {
page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; }
#doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button,
#doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border:
none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding:
10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; }
body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf }
body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-
color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; }
body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; }
jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf');
jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href",
"https://valleywidepro.com/estimate/f782a5846a78114204f60f3584125830/"); jQuery(".button.primary_button.purchase_button").attr("href",
"https://valleywidepro.com/estimate/f782a5846a78114204f60f3584125830/"); jQuery(".button.primary_button.payment_option").attr("href",
"https://valleywidepro.com/estimate/f782a5846a78114204f60f3584125830/"); jQuery("#change_payment_amount").attr("href",
"https://valleywidepro.com/estimate/f782a5846a78114204f60f3584125830/"); });
```

(6216) PATIO ROOF REPLACE – 10358 N 78TH AVE

.button.status_change, a.button.primary_button.purchase_button, a.button.primary_button.payment_option { display: none; } .stipe_checkout_button { display: none; } .square_checkout { display: none; } .button.status_change[data-status-change=decline] { display: inline-block !important; }

[Decline Estimate](#)

[Signature Required](#)

[Print to PDF](#)

[Accept Estimate](#)

Belén Rodríguez
10358 N 78TH AVE
PEORIA, AZ 85345
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US



Date

May 29, 2025



Estimate Number

6216



Estimate Due

June 28, 2025

Estimate Total

\$5,250.00

Service	Price	Amount
<ul style="list-style-type: none"> • This estimate applies to the entire patio @ 9 sq's. • Remove rolled roofing from the patio. • Remove and replace fascia board and trim from patio as needed. • Remove and replace plywood as needed @ \$80 per sheet • Includes 4 sheets • Apply new SA-SBS Rolled Roofing Peel Stick Basesheet and Capsheet over the entire patio. • Install 2inch x 2inch drip edge around the perimeter of the entire patio as needed. • Tie the patio roof into the main structure as needed. (shingle roof) • Seal all penetrations, haul away debris and keep yard clean. • Provide 10 year warranty against leaks over the entire patio, @ 9 sq's. <p>WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed. Tax is included in price: \$3,800</p> <p>Upon inspecting attic and rafters we have 3 issues. A cracked rafter, and 2 rafter supports installed improperly and need to be corrected. +\$1,450</p> <p>ESTIMATED COMPLETION: 1 DAY</p> <p>WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed. Tax is included in price.</p>	\$5,250	\$5,250

	Subtotal	\$0.00
	Total	\$5,250.00

Upon inspecting the patio visible damages are noticeable. The cap sheet of the patio has been coated with elastomeric coating to cover up the damages and to extend the life of the Roof. And the longest side of the patio. There has been a separate drip edge installed over the existing roof. This was to hold down and prevent from lifting any further. Nothing else. Replacement is what's recommended for this roof.

Thank you; we really appreciate your business! Let us know if you have any questions about your estimate.

To approve this estimate, 50% is due prior to the beginning of the project. 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Phone: (877) 692-9762

Email: info@azroc.gov

Address: Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812

Website: www.azroc.gov

Please reference our license number ROC# 348219 when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

To approve this estimate, 50% is due prior to the beginning of the project.

Save Signature!



 **Updated**
May 29, 2025 @ 1:27 pm

Estimate updated by valleywide.

 **Viewed**
May 29, 2025 @ 1:28 pm

Estimate viewed by (valleywide) for the first time.

 **Viewed**
May 29, 2025 @ 1:28 pm

Estimate viewed by Belén Rodríguez (azstateliving@gmail.com) for the first time.

 **Updated**
May 29, 2025 @ 1:29 pm

Estimate updated by valleywide.

 **Viewed**
May 29, 2025 @ 1:29 pm


Estimate viewed by for the first time.

 **Updated**
May 29, 2025 @ 1:48 pm

Estimate updated by valleywide.

 **Viewed**
May 29, 2025 @ 1:50 pm

Estimate viewed by 162.158.186.41 for the first time.

 **Updated**
May 29, 2025 @ 1:50 pm

Estimate updated by valleywide.

 **Viewed**
May 29, 2025 @ 1:51 pm

Estimate viewed by 172.69.74.218 for the first time.

 **Updated**
May 29, 2025 @ 3:27 pm

Estimate updated by valleywide.

 Viewed
May 30, 2025 @ 9:14 pm

Estimate viewed by 172.69.74.210 for the first time.

 Viewed
May 30, 2025 @ 9:14 pm

Estimate viewed by 172.70.130.244 for the first time.

 Viewed
May 30, 2025 @ 9:15 pm

Estimate viewed by 172.71.255.67 for the first time.

 Viewed
June 3, 2025 @ 10:10 am

Estimate viewed by 162.158.175.182 for the first time.

 Viewed
June 3, 2025 @ 1:19 pm

Estimate viewed by 172.69.74.219 for the first time.

 Viewed
June 3, 2025 @ 1:46 pm

Estimate viewed by 104.23.195.23 for the first time.

 Viewed
June 3, 2025 @ 7:45 pm

Estimate viewed by 172.70.127.159 for the first time.

 Viewed
June 4, 2025 @ 7:11 am

Estimate viewed by 172.69.74.211 for the first time.

 Viewed
June 4, 2025 @ 7:11 am

Estimate viewed by 172.69.74.234 for the first time.

 Viewed
June 5, 2025 @ 3:08 am

Estimate viewed by 108.162.216.126 for the first time.

 Viewed
June 5, 2025 @ 9:01 am

Estimate viewed by 172.69.17.156 for the first time.

 Viewed
July 1, 2025 @ 5:31 pm

Estimate viewed by 172.69.59.65 for the first time.

 Viewed

July 5, 2025 @ 6:43 am

Estimate viewed by 162.158.170.185 for the first time.



 Viewed

September 14, 2025 @ 3:59 am

Estimate viewed by 172.69.17.67 for the first time.



 Viewed

September 17, 2025 @ 12:48 am

Estimate viewed by 172.70.140.205 for the first time.



 Viewed

September 18, 2025 @ 9:43 pm

Estimate viewed by 172.71.254.131 for the first time.



 Viewed

September 20, 2025 @ 11:42 am

Estimate viewed by 198.41.230.190 for the first time.



 Viewed

September 21, 2025 @ 12:13 pm

Estimate viewed by 172.71.234.102 for the first time.



 Viewed

September 22, 2025 @ 7:03 pm

Estimate viewed by 172.69.138.141 for the first time.



 Viewed

September 24, 2025 @ 8:32 am

Estimate viewed by 108.162.226.229 for the first time.



 Viewed

September 25, 2025 @ 9:26 pm

Estimate viewed by 172.69.34.139 for the first time.



 Viewed

September 29, 2025 @ 8:03 pm

Estimate viewed by 172.64.204.165 for the first time.



 Viewed

October 1, 2025 @ 10:57 am

Estimate viewed by 172.71.218.198 for the first time.



 Viewed

October 5, 2025 @ 1:20 am

Estimate viewed by 104.23.254.178 for the first time.



 Viewed

October 5, 2025 @ 1:22 am

Estimate viewed by 172.69.90.163 for the first time.

 Viewed

October 7, 2025 @ 2:32 am

Estimate viewed by 172.71.25.134 for the first time.

 Viewed

October 8, 2025 @ 12:05 pm

Estimate viewed by 172.69.138.97 for the first time.

 Viewed

October 9, 2025 @ 7:31 pm

Estimate viewed by 172.69.39.24 for the first time.

 Viewed

October 12, 2025 @ 11:37 am

Estimate viewed by 172.69.11.52 for the first time.

 Viewed

October 13, 2025 @ 5:59 pm

Estimate viewed by 162.158.189.102 for the first time.

 Viewed

October 22, 2025 @ 6:13 pm

Estimate viewed by 172.70.224.142 for the first time.

 Viewed

October 25, 2025 @ 11:30 am

Estimate viewed by 172.71.218.113 for the first time.

 Viewed

October 27, 2025 @ 10:57 am

Estimate viewed by 172.68.234.97 for the first time.

 Viewed

October 30, 2025 @ 2:17 am

Estimate viewed by 172.69.17.110 for the first time.

 Viewed

November 22, 2025 @ 2:54 am

Estimate viewed by 104.23.209.99 for the first time.

 Viewed

December 4, 2025 @ 7:18 am

Estimate viewed by 162.158.170.238 for the first time.

 Viewed

January 15, 2026 @ 8:23 am

Estimate viewed by 172.71.254.32 for the first time.

 Viewed

January 16, 2026 @ 12:30 am

Estimate viewed by 198.41.230.148 for the first time.

 Viewed

January 16, 2026 @ 11:44 pm

Estimate viewed by 108.162.216.146 for the first time.

 Viewed

January 18, 2026 @ 12:14 am

Estimate viewed by 172.70.126.41 for the first time.

 Viewed

January 18, 2026 @ 1:42 am

Estimate viewed by 172.69.17.66 for the first time.

 Viewed

January 18, 2026 @ 1:42 am

Estimate viewed by 172.69.59.155 for the first time.

 Viewed

February 3, 2026 @ 11:10 pm

Estimate viewed by 172.70.175.137 for the first time.

 Viewed

February 6, 2026 @ 3:12 am

Estimate viewed by 104.23.239.144 for the first time.

 Viewed

March 3, 2026 @ 8:43 pm

Estimate viewed by 104.22.64.81 for the first time.

 Viewed

March 4, 2026 @ 5:57 am

Estimate viewed by 172.69.7.15 for the first time.

 Viewed

March 4, 2026 @ 10:47 am

Estimate viewed by 172.70.126.103 for the first time.

 Viewed

March 10, 2026 @ 11:42 pm

Estimate viewed by 172.71.254.254 for the first time.

-  **Viewed**
March 19, 2026 @ 10:06 pm
Estimate viewed by 172.69.59.156 for the first time.
-  **Viewed**
March 20, 2026 @ 1:46 pm
Estimate viewed by 172.70.126.102 for the first time.
-  **Viewed**
March 21, 2026 @ 10:47 pm
Estimate viewed by 104.22.62.107 for the first time.
-  **Viewed**
March 23, 2026 @ 9:40 am
Estimate viewed by 172.69.7.16 for the first time.
-  **Viewed**
March 24, 2026 @ 4:51 pm
Estimate viewed by 172.71.255.2 for the first time.
-  **Viewed**
March 26, 2026 @ 10:38 pm
Estimate viewed by 172.69.17.138 for the first time.
-  **Viewed**
March 27, 2026 @ 10:00 pm
Estimate viewed by 104.22.62.106 for the first time.
-  **Viewed**
April 25, 2026 @ 8:29 am
Estimate viewed by 162.158.167.169 for the first time.
-  **Viewed**
April 26, 2026 @ 10:22 pm
Estimate viewed by 172.68.211.221 for the first time.
-  **Viewed**
April 28, 2026 @ 6:49 am
Estimate viewed by 162.158.193.213 for the first time.
-  **Viewed**
April 29, 2026 @ 8:44 am
Estimate viewed by 172.64.200.92 for the first time.
-  **Viewed**
May 28, 2026 @ 1:18 am
Estimate viewed by 172.69.17.139 for the first time.



