

```
body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals { page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; } #doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button, #doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border: none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding: 10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; } body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf } body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; } body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; } jQuery(document).ready(function() { jQuery("#invoice.sa_invoice-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("#estimate.sa_estimate-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href", "https://valleywidepro.com/estimate/052b795ea92a5903ee75df61bd34f612/"); jQuery(".button.primary_button.purchase_button").attr("href", "https://valleywidepro.com/estimate/052b795ea92a5903ee75df61bd34f612/"); jQuery(".button.primary_button.payment_option").attr("href", "https://valleywidepro.com/estimate/052b795ea92a5903ee75df61bd34f612/"); jQuery("#change_payment_amount").attr("href", "https://valleywidepro.com/estimate/052b795ea92a5903ee75df61bd34f612/"); });
```

(9663) TILE ROOF REPLACE – 3642 W BARCELONA DR

Print to PDF

Accept Estimate

Decline Estimate

Sharon Kurpius

3642 W Barcelona Dr
Chandler, AZ 85226
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US



Date

October 16, 2025



Estimate Number

9663



Estimate Due

November 15, 2025



Estimate Total

\$1.00

Service

Price

Amount

ESTIMATE SPECS FOR TILE ROOF REPLACE *PLEASE SEE ROOFR
SPECS ATTACHED*

\$0

\$0

- This proposal applies to the entire Tile Roof @ 46 sq's.
- Remove tile then set aside, re-install after repair (unless broken—then replace).
- Remove felt and remove and replace battens from the entire tile roof.
- Remove and replace any sheets of bad plywood (as needed) throughout the roof. *Additional plywood billed at \$85/sheet.*
- Repair/replace rolled composition roofing as needed.
- Install new [SEE BELOW] underlayment over the entire tile roof.
- Install new 3 inch x 3 inch drip edge around the perimeter of the entire tile roof.
- Install new ribbed valley metals, and channel metals as needed throughout the tile roof.
- Install new L metals, roof jacks, T-Top air vents, and O'Haggin vents throughout the tile roof as needed. (proper ventilation)
- Install all new Fascia Board as needed.
- Repair the soffits as needed throughout the tile roof.
- Repair/replace exterior supports as needed.
- Repair/replace attic access covers as needed.
- Repair/replace downspout extensions (not installed) as needed.
- Install new ridge and hip enclosures as needed throughout the tile roof.
- Install new bird stops as needed throughout the tile roof.
- Seal all penetrations, haul away debris and keep yard clean.
- Provide [30-YEAR] limited warranty against leaks over the entire Tile roof, @ 46 sq's.

ESTIMATED COMPLETION: 3-4 Days

WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed. Tax is included in price.

PROJECT OPTIONS:

- **GOOD: TRIBUILT HYBRID UNDERLAYMENT – \$18,900 + 15-YEAR MANUFACTURER'S WARRANTY***
- **BETTER: GATOR SEAL UNDERLAYMENT – \$20,600 + 20-YEAR MANUFACTURER'S WARRANTY***
- **BEST: (OPTION ONE: DOUBLE-LAYER TRI-BUILT HYBRID | OPTION TWO: WESTLAKE TILESEAL) UNDERLAYMENT – \$22,000 + 30-YEAR MANUFACTURER'S WARRANTY***

**See warranty statement below.*

Subtotal	\$0.00
Total	\$1.00

Thank you; we really appreciate your business! Let us know if you have any questions about your estimate.

Please see attachments for full roof report information.

50% is due prior to the beginning of the project. 50% due upon completion.

At Valleywide Pro Roofing, LLC, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Phone: (877) 692-9762
Email: info@azroc.gov
Address: Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812
Website: www.azroc.gov

Please reference our license number [ROC# 348219](#) when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

Warranty Statement for Roof Replacement Options

Thank you for choosing Valleywide Pro Roofing, LLC for your roofing needs. We are committed to providing high-quality materials and professional installation to ensure the longevity and performance of your new roof. To maximize the lifespan of your roof and maintain warranty coverage, the following warranty terms and conditions apply:

1. Warranty Coverage

All roof replacement options come with a comprehensive warranty that includes:

Underlayment Warranty: Coverage as per the manufacturer's warranty, ranging from 10 to 50 years depending on the underlayment type selected.

Tile Warranty: Coverage as per the manufacturer's warranty, ranging from 30 years to a lifetime, depending on the type of tile selected (standard concrete, premium concrete, or clay tiles).

2. Maintenance Requirements

To maintain the validity of the warranty beyond the initial 15 years, an **annual maintenance package** is required. This package is designed to ensure your roof remains in optimal condition and any potential issues are addressed promptly.

Annual Maintenance Package Cost: \$299/year.

Discounted Maintenance Plan: Customers have the option to pre-pay for maintenance in 5-year bundles at a discounted rate. See below for discounts.

Discounted Rates:

5-Year Maintenance Bundle: \$1,345 (a savings of \$150 compared to annual payments).

3. Manufacturer Warranty Claims

While Valleywide Pro Roofing, LLC provides a workmanship warranty on the installation and materials used, any claims related to the manufacturer's warranties (underlayment and tiles) must be processed directly through the manufacturer. Our team is available to assist you in facilitating these claims to ensure a smooth and efficient process.

4. Terms and Conditions

Warranty Activation: The warranty will become effective on the date of completion of the roof installation.

Maintenance Schedule: The annual maintenance package is mandatory after the initial 5-year period to continue the coverage. Failure to comply with the annual maintenance schedule may void the warranty.

Coverage Exclusions: The warranty does not cover damage caused by natural disasters, improper use, or modifications made to the roof after installation without prior consultation with Valleywide Pro Roofing, LLC. The warranty does not cover any work performed by other roofing contractors or companies not associated with Valleywide Pro Roofing, LLC.

Warranty Transfer: The warranty is transferable to a new homeowner upon the sale of the property, provided that all maintenance requirements have been met. A **one-time transfer fee of \$250** is required to transfer the warranty to the new homeowner.

We appreciate your business and are dedicated to providing you with a roof that offers protection and peace of mind for years to come. If you have any questions regarding the warranty or maintenance packages, please do not hesitate to contact us.

<https://valleywidepro.com> billing@valleywidepro.com



Updated

Estimate updated by valleywide.

October 16, 2025 @ 2:57 pm



Updated

Estimate updated by valleywide.

October 16, 2025 @ 2:58 pm



Updated

Estimate updated by valleywide.

October 20, 2025 @ 9:25 am



Viewed

Estimate viewed by (valleywide) for the first time.

October 20, 2025 @ 9:25 am



Updated

Estimate updated by valleywide.

October 20, 2025 @ 9:31 am



Viewed

Estimate viewed by for the first time.

October 20, 2025 @ 9:32 am



Viewed

Estimate viewed by 172.70.111.167 for the first time.

October 20, 2025 @ 9:32 am

 Updated

October 20, 2025 @ 9:33 am

Estimate updated by valleywide.

 Viewed

October 20, 2025 @ 9:53 am

Estimate viewed by 104.23.251.90 for the first time.

 Viewed

October 20, 2025 @ 10:21 am

Estimate viewed by Sharon Kurpius (azbolger7@gmail.com) for the first time.

 Viewed

October 21, 2025 @ 1:11 pm

Estimate viewed by 162.158.90.35 for the first time.

 Viewed

October 30, 2025 @ 2:21 am

Estimate viewed by 172.71.255.126 for the first time.

 Viewed

November 14, 2025 @ 2:53 pm

Estimate viewed by 104.23.251.91 for the first time.

 Viewed

November 26, 2025 @ 6:07 am

Estimate viewed by 172.69.59.148 for the first time.

 Viewed

November 26, 2025 @ 6:10 am

Estimate viewed by 172.70.194.133 for the first time.

 Viewed

November 30, 2025 @ 1:05 pm

Estimate viewed by 172.71.195.89 for the first time.

 Viewed

December 5, 2025 @ 4:13 pm

Estimate viewed by 172.68.164.48 for the first time.

 Viewed

December 7, 2025 @ 9:57 am

Estimate viewed by 172.70.126.40 for the first time.

 Viewed

December 14, 2025 @ 4:24 am

Estimate viewed by 172.70.179.45 for the first time.

 Viewed

February 3, 2026 @ 5:03 pm

Estimate viewed by 172.71.223.6 for the first time.

 Viewed

February 6, 2026 @ 3:10 am

Estimate viewed by 172.71.148.37 for the first time.

 Viewed

March 7, 2026 @ 4:07 pm

Estimate viewed by 104.23.205.145 for the first time.

 Viewed

March 13, 2026 @ 1:59 pm

Estimate viewed by 172.70.215.93 for the first time.

 Viewed

March 14, 2026 @ 10:17 pm

Estimate viewed by 108.162.216.153 for the first time.

 Viewed

April 2, 2026 @ 6:47 am

Estimate viewed by 172.68.175.79 for the first time.

 Viewed

April 2, 2026 @ 6:47 am

Estimate viewed by 172.71.146.225 for the first time.

 Viewed

April 2, 2026 @ 6:47 am

Estimate viewed by 172.71.150.246 for the first time.

 Viewed

April 20, 2026 @ 4:42 am

Estimate viewed by 172.69.59.155 for the first time.

 Viewed

April 25, 2026 @ 1:30 am

Estimate viewed by 162.158.167.169 for the first time.

 Viewed

April 27, 2026 @ 12:09 am

Estimate viewed by 162.158.88.77 for the first time.

 Viewed

April 28, 2026 @ 6:58 am

Estimate viewed by 172.68.211.221 for the first time.

Estimate viewed by 172.68.192.192 for the first time.

 Viewed 

April 29, 2026 @ 8:44 am