

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:"ctlSignature",SignWidth:
"450",TransparentSign:"true",SignHeight:"300",IsModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor:
"#FFFFFF", BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-
pro/bundles/sprout-invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-
invoices-pro/bundles/sprout-invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.",
ErrorMessage: "Please continue with a valid signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.",
SignzIndex: 1000, Visible: "true", forceMouseEvent: true, Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init();
$("#sign_doc").on('click', function(event) { event.preventDefault(); // scroll to signature $('html, body').animate({ scrollTop:
$("#ctlSignature_Container").offset().top }, 1000); }); $("#save_signature_via_ajax").on('click', function(event) { if (! ValidateSignature() ) { return; }
var sig_data = $("#ctlSignature_data").val(), sig_data_smooth = $("#ctlSignature_data_canvas").val(); $(this).after(si_js_object.inline_spinner);
$.post( si_js_object.ajax_url, { action: 'si_save_signature', invoice_id: 8899, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce:
si_js_object.security }, function( response ) { $('#spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $('#sign_doc').hide();
$('#ctlSignature_toolbar').hide(); // show signature $('#si_signature_wrap').html( response.data.img ); // Add ability to pay $(
'stipe_checkout_button').show(); $('#square_checkout').show(); $('#button.status_change').show(); $('#a.button.primary_button.purchase_button'
).show(); $('#a.button.primary_button.payment_option').show(); // New Theme $('#paybar.inner.button.open').show(); // scroll to the top $('html,
body').animate({ scrollTop: $('#outer_doc_wrap').offset().top }, 500); } else { $("#save_signature_via_ajax").after(" + response.data.message + "); }
}); //]]> body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals {
page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; }
#doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button,
#doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border:
none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding:
10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; }
body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf }
body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-
color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; }
body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; }
jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf');
jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href",
"https://valleywidepro.com/estimate/139f1023ff292949ae451d44b9a70b9a/"); jQuery(".button.primary_button.purchase_button").attr("href",
"https://valleywidepro.com/estimate/139f1023ff292949ae451d44b9a70b9a/"); jQuery(".button.primary_button.payment_option").attr("href",
"https://valleywidepro.com/estimate/139f1023ff292949ae451d44b9a70b9a/"); jQuery("#change_payment_amount").attr("href",
"https://valleywidepro.com/estimate/139f1023ff292949ae451d44b9a70b9a/"); });
```

(8899) NEW BUILD TILE ROOF INSTALL – 24511 S 123RD ST

.button.status_change, a.button.primary_button.purchase_button, a.button.primary_button.payment_option { display: none; } .stipe_checkout_button { display: none; } .square_checkout { display: none; } .button.status_change[data-status-change=decline] { display: inline-block !important; }

[Decline Estimate](#)

[Signature Required](#)

[Print to PDF](#)

[Accept Estimate](#)

Nico Nava
7655 E Windrose Dr.
Scottsdale, AZ 85260



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US



Date

September 24, 2025



Estimate Number

8899



Estimate Due

October 24, 2025



Estimate Total

\$59,700.00

Service	Price	Amount
<p>ESTIMATE SPECS FOR NEW BUILD TILE ROOF INSTALLATION *PLEASE SEE ROOFR SPECS ATTACHED*</p> <ul style="list-style-type: none"> • —This proposal applies to the NEW BUILD ROOF INSTALL @ 69 sq's. • —Install new HT WEST LAKE TILE SEAL underlayment over the entire new roof. • —Install new BATTENS over the entire new roof. • —Install new SBS ROLLED ROOFING as needed over the entire new roof. • —Install new FLAT-STYLE tile in gray over the entire new roof. • —Install new 3 inch x 3 inch drip edge around the perimeter of the entire new roof. • —Install new 3-ribbed valley metals and channel metals as needed throughout the new roof. • —Install new L metals, roof jacks, T-Top air vents and O'Haggin vents throughout the new roof as needed for proper ventilation. • —Install new skylight and new flashing on the new roof. • —Install new ridge and hip enclosures as needed throughout the new roof. • —Seal all penetrations, haul away debris and keep yard clean. • —Provide 30-YEAR limited warranty against leaks over the entire new tile roof, @ 69 sq's. <p>ESTIMATED COMPLETION: 8-14 Days</p> <p>WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed. Tax is included in price.</p> <p>*See warranty statement below.</p>	<p>\$59,700</p>	<p>\$59,700</p>

	<p>Subtotal \$0.00</p>
	<p>Total \$59,700.00</p>

Thank you; we really appreciate your business! Let us know if you have any questions about your estimate.

Please see attachments for full roof report information.

50% is due prior to the beginning of the project. 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, LLC, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Phone: (877) 692-9762

Email: info@azroc.gov

Address: Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812

Website: www.azroc.gov

Please reference our license number [ROC# 348219](#) when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

Warranty Statement for Roof Replacement Options

Thank you for choosing Valleywide Pro Roofing, LLC for your roofing needs. We are committed to providing high-quality materials and professional installation to ensure the longevity and performance of your new roof. To maximize the lifespan of your roof and maintain warranty coverage, the following warranty terms and conditions apply:

1. Warranty Coverage

All roof replacement options come with a comprehensive warranty that includes:

Underlayment Warranty: Coverage as per the manufacturer's warranty, ranging from 10 to 50 years depending on the underlayment type selected.

Tile Warranty: Coverage as per the manufacturer's warranty, ranging from 30 years to a lifetime, depending on the type of tile selected (standard concrete, premium concrete, or clay tiles).

2. Maintenance Requirements

To maintain the validity of the warranty beyond the initial 15/20/30 years, an **annual maintenance package** is required. This package is designed to ensure your roof remains in optimal condition and any potential issues are addressed promptly.

Annual Maintenance Package Cost: \$299/year.

Discounted Maintenance Plan: Customers have the option to pre-pay for maintenance in 5-year bundles at a discounted rate. See below for discounts.

Discounted Rates:

5-Year Maintenance Bundle: \$1,345 (a savings of \$150 compared to annual payments).

3. Manufacturer Warranty Claims

While Valleywide Pro Roofing, LLC provides a workmanship warranty on the installation and materials used, any claims related to the manufacturer's warranties (underlayment and tiles) must be processed directly through the manufacturer. Our team is available to assist you in facilitating these claims to ensure a smooth and efficient process.

4. Terms and Conditions

Warranty Activation: The warranty will become effective on the date of completion of the roof installation.

Maintenance Schedule: The annual maintenance package is mandatory after the initial 5-year period to continue the coverage. Failure to comply with the annual maintenance schedule may void the warranty.

Coverage Exclusions: The warranty does not cover damage caused by natural disasters, improper use, or modifications made to the roof after installation without prior consultation with Valleywide Pro Roofing, LLC. The warranty does not cover any work performed by other roofing contractors or companies not associated with Valleywide Pro Roofing, LLC.

Warranty Transfer: The warranty is transferable to a new homeowner upon the sale of the property, provided that all maintenance requirements have been met. A **one-time transfer fee of \$250** is required to transfer the warranty to the new homeowner.

We appreciate your business and are dedicated to providing you with a roof that offers protection and peace of mind for years to come. If you have any questions regarding the warranty or maintenance packages, please do not hesitate to contact us.

Save Signature!

<https://valleywidepro.com> billing@valleywidepro.com



 Updated

September 24, 2025 @ 10:59 pm

Estimate updated by valleywide.

 Viewed

September 24, 2025 @ 11:00 pm

Estimate viewed by (valleywide) for the first time.

 Viewed

September 24, 2025 @ 11:00 pm

Estimate viewed by for the first time.

 Viewed

September 24, 2025 @ 11:00 pm

Estimate viewed by 104.23.195.81 for the first time.

 Viewed

September 25, 2025 @ 8:12 pm

Estimate viewed by 172.69.74.253 for the first time.

 Viewed

September 25, 2025 @ 8:12 pm

Estimate viewed by 172.69.74.211 for the first time.

 Viewed

October 16, 2025 @ 11:34 am

Estimate viewed by 104.23.195.57 for the first time.

 Viewed

October 16, 2025 @ 11:35 am

Estimate viewed by 104.23.195.80 for the first time.

 Viewed

October 18, 2025 @ 12:23 pm

Estimate viewed by 172.68.35.64 for the first time.

 Viewed

October 19, 2025 @ 7:39 pm

Estimate viewed by 172.69.74.219 for the first time.

 Viewed

October 24, 2025 @ 7:06 am

Estimate viewed by 162.158.187.51 for the first time.

 Viewed

October 30, 2025 @ 2:21 am

Estimate viewed by 172.69.58.45 for the first time.

Estimate viewed by 104.23.237.111 for the first time.

 Viewed

November 6, 2025 @ 1:49 am

Estimate viewed by 172.69.59.148 for the first time.

 Viewed

November 6, 2025 @ 1:50 am

 Viewed

November 23, 2025 @ 8:21 am

Estimate viewed by 172.70.176.41 for the first time.

 Viewed

November 25, 2025 @ 11:53 pm

Estimate viewed by 172.71.254.32 for the first time.

 Viewed

November 25, 2025 @ 11:57 pm

Estimate viewed by 172.71.254.76 for the first time.

 Viewed

December 5, 2025 @ 1:13 am

Estimate viewed by 172.68.242.93 for the first time.

 Viewed

December 10, 2025 @ 4:42 am

Estimate viewed by 172.70.100.99 for the first time.

 Viewed

January 14, 2026 @ 11:35 am

Estimate viewed by 172.70.147.199 for the first time.

 Viewed

February 3, 2026 @ 11:33 am

Estimate viewed by 172.70.111.158 for the first time.

 Viewed

February 6, 2026 @ 3:11 am

Estimate viewed by 104.23.239.107 for the first time.

 Viewed

March 1, 2026 @ 3:19 pm

Estimate viewed by 172.70.126.41 for the first time.

 Viewed

March 13, 2026 @ 1:59 pm

Estimate viewed by 172.70.215.93 for the first time.

 Viewed

March 17, 2026 @ 6:51 pm

Estimate viewed by 172.71.167.76 for the first time.



Viewed

March 19, 2026 @ 11:35 pm

Estimate viewed by 172.70.94.138 for the first time.



Viewed

March 19, 2026 @ 11:35 pm

Estimate viewed by 198.41.227.74 for the first time.



Viewed

March 20, 2026 @ 2:39 pm

Estimate viewed by 172.70.126.103 for the first time.



Viewed

March 22, 2026 @ 10:05 pm

Estimate viewed by 172.69.59.155 for the first time.



Viewed

March 23, 2026 @ 8:51 am

Estimate viewed by 172.70.126.102 for the first time.



Viewed

March 23, 2026 @ 8:51 am

Estimate viewed by 104.22.62.106 for the first time.



Viewed

March 25, 2026 @ 9:32 am

Estimate viewed by 104.22.62.107 for the first time.



Viewed

March 26, 2026 @ 11:23 pm

Estimate viewed by 172.69.17.139 for the first time.



Viewed

March 26, 2026 @ 11:23 pm

Estimate viewed by 172.69.59.152 for the first time.



Viewed

April 25, 2026 @ 5:17 pm

Estimate viewed by 104.22.17.145 for the first time.



Viewed

April 28, 2026 @ 9:48 am

Estimate viewed by 162.158.179.114 for the first time.



Viewed

April 29, 2026 @ 8:44 am

Estimate viewed by 172.64.223.135 for the first time.



