

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:"ctlSignature",SignWidth:
'450",TransparentSign:"true",SignHeight: "300",leModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor:
"#FFFFFF", BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-
pro/bundles/sprout-invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-
invoices-pro/bundles/sprout-invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.",
ErrorMessage: "Please continue with a valid signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.",
SignzIndex: 1000, Visible: "true", forceMouseEvent: true, Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init();
$("#sign_doc").on('click', function(event) { event.preventDefault(); // scroll to signature $('html, body').animate({ scrollTop:
$("#ctlSignature_Container").offset().top }, 1000); }); $("#save_signature_via_ajax").on('click', function(event) { if (! ValidateSignature() ) { return; }
var sig_data = $("#ctlSignature_data").val(), sig_data_smooth = $("#ctlSignature_data_canvas").val(); $(this).after(si_js_object.inline_spinner);
$.post( si_js_object.ajax_url, { action: 'si_save_signature', invoice_id: 643, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce:
si_js_object.security }, function( response ) { $('spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $('#sign_doc').hide();
$("#ctlSignature_toolbar").hide(); // show signature $('#si_signature_wrap').html( response.data.img ); // Add ability to pay $(
'stipe_checkout_button').show(); $('#square_checkout').show(); $('#button.status_change').show(); $('#a.button.primary_button.purchase_button'
).show(); $('#a.button.primary_button.payment_option').show(); // New Theme $('#paybar.inner.button.open').show(); // scroll to the top $('html,
body').animate({ scrollTop: $("#outer_doc_wrap").offset().top }, 500); } else { $("#save_signature_via_ajax").after(" + response.data.message + "); }
}); //]]> body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals {
page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; }
#doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button,
#doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border:
none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding:
10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; }
body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf }
body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-
color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; }
body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; }
jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf');
jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href",
"https://valleywidepro.com/estimate/1fe36fb4458c7f01147dc10db030f399/"); jQuery(".button.primary_button.purchase_button").attr("href",
"https://valleywidepro.com/estimate/1fe36fb4458c7f01147dc10db030f399/"); jQuery(".button.primary_button.payment_option").attr("href",
"https://valleywidepro.com/estimate/1fe36fb4458c7f01147dc10db030f399/"); jQuery("#change_payment_amount").attr("href",
"https://valleywidepro.com/estimate/1fe36fb4458c7f01147dc10db030f399/"); });
```

Tile Roof – Gerald Arndt

.button.status_change, a.button.primary_button.purchase_button, a.button.primary_button.payment_option { display: none; } .stipe_checkout_button { display: none; } .square_checkout { display: none; } .button.status_change[data-status-change=decline] { display: inline-block !important; }

Decline Estimate

Signature Required

Print to PDF

Accept Estimate

Gerald Arndt
5801 SOUTH 53RD GLENN
Laveen, AZ 85339
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US



Date

October 18, 2023



Estimate Number

643



Estimate Due

November 17, 2023

Estimate Total

\$0.00

Task	Rate	Qty	%	Amount
<p>ESTIMATE SPECS FOR TILE ROOF REPLACE</p> <ul style="list-style-type: none"> —This proposal applies to the entire Tile Roof @ 23 sq's. —Remove tile then set aside, re-install after repair (unless broken—then replace). —Remove felt and remove and replace battens from the entire roof. —Remove and replace sheets of bad plywood (as needed) throughout the ROOF. Additional plywood billed at \$80/sheet. —Install {sbs} sq's of new SBS rolled roofing in any death valleys and behind the chimney as needed. —Install a single of new Good,better or best Underlayment over the entire roof. —Install { new 3inch x 3inch drip edge around the perimeter of the entire roof. —Install new 3 ribbed valley metals, and {channel_metals} channel metals as needed throughout the ROOF. —Install {_metals} new L metals, {roof_jacks} roof jacks, {t_top_vents} T-Top air vents, and {o_hagins} O'Hagin vents throughout the roof. (proper ventilation. —Install new ridge and hip enclosures as needed throughout the roof. —Install new bird stops as needed throughout the tile roof —Seal all penetrations, haul away debris and keep yard clean. —Provide {see below} warranty against leaks over the entire Tile roof, @ {23} sq's. <p>ESTIMATED COMPLETION: {2-3} Days</p> <p>WE PROPOSE hereby to furnish material and labor – complete in accordance with</p>	\$0	1	0%	\$0

the above specifications, for the sum listed below. Tax is included in price.

**UNDERLAYMENT TYPE
DETERMINES PRICING PER SQ:**

GOOD: (\$11,700} 15 year warranty

<https://westlakeroyalroofing.c...>

BETTER: {12,400} 20 year warranty

<https://westlakeroyalroofing.c...>

BEST: {14,500} 30 year warranty

<https://westlakeroyalroofing.c...>

Patio: (1,300) 20 year warranty

Subtotal	\$0.00
Total	\$0.00

Thank you; we really appreciate your business! Please be sure to leave us a review upon completion of your project – we reward any reviews with a gift card. Referrals are our lifeline, please tell your neighbors about Valleywide!

Here is a link of the walk-through of your roof: https://bbemaildelivery.com/bbext/?p=video_land&id=d8c4c0a0-6509-4a28-a82e-b0218ad1a7d1

Please let me know if you have any questions. Carlos Mendivil 602-814-3862

ACCEPTANCE OF PROPOSAL: These prices, specifications, and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified.

To approve this estimate, 50% is due prior to the beginning of the project.

Save Signature!



-  **Viewed**
October 18, 2023 @ 6:39 pm
Estimate viewed by 172.70.130.132 for the first time.
-  **Viewed**
October 18, 2023 @ 6:40 pm
Estimate viewed by 108.162.216.141 for the first time.
-  **Viewed**
October 18, 2023 @ 6:40 pm
Estimate viewed by 172.69.59.118 for the first time.
-  **Updated**
October 24, 2023 @ 10:51 am
Estimate updated by valleywide.
-  **Viewed**
October 24, 2023 @ 10:54 am
Estimate viewed by 172.70.131.113 for the first time.
-  **Viewed**
October 24, 2023 @ 1:52 pm
Estimate viewed by 162.158.186.128 for the first time.
-  **Viewed**
October 25, 2023 @ 8:05 am
Estimate viewed by for the first time.

 Viewed

October 25, 2023 @ 8:05 am

Estimate viewed by 172.71.254.237 for the first time.

 Viewed

October 25, 2023 @ 8:05 am

Estimate viewed by 172.70.175.144 for the first time.

 Viewed

January 9, 2024 @ 8:20 pm

Estimate viewed by 172.70.214.33 for the first time.

 Viewed

March 24, 2024 @ 6:22 am

Estimate viewed by 162.158.102.200 for the first time.

 Viewed

July 11, 2024 @ 2:02 pm

Estimate viewed by 108.162.210.234 for the first time.

 Viewed

February 11, 2025 @ 12:12 am

Estimate viewed by 172.70.131.131 for the first time.

 Viewed

February 14, 2025 @ 2:41 am

Estimate viewed by 172.69.6.78 for the first time.

 Viewed

February 23, 2025 @ 1:25 pm

Estimate viewed by 172.71.254.59 for the first time.

 Viewed

March 1, 2025 @ 2:03 pm

Estimate viewed by 162.158.106.70 for the first time.

 Viewed

March 9, 2025 @ 2:15 pm

Estimate viewed by 172.70.179.117 for the first time.

 Viewed

March 15, 2025 @ 9:49 pm

Estimate viewed by 162.158.190.103 for the first time.

 Viewed

April 29, 2025 @ 9:27 pm

Estimate viewed by 172.69.17.64 for the first time.

 Viewed

May 30, 2025 @ 2:43 pm

Estimate viewed by 172.70.126.59 for the first time.

 Viewed

June 4, 2025 @ 12:25 am

Estimate viewed by 172.70.127.64 for the first time.

 Viewed

June 5, 2025 @ 3:12 am

Estimate viewed by 172.69.17.133 for the first time.

 Viewed

June 5, 2025 @ 9:01 am

Estimate viewed by 172.71.1.160 for the first time.

 Viewed

June 9, 2025 @ 10:17 pm

Estimate viewed by 172.70.178.23 for the first time.

 Viewed

June 11, 2025 @ 9:46 am

Estimate viewed by 172.69.58.97 for the first time.

 Viewed

June 19, 2025 @ 10:35 pm

Estimate viewed by 172.69.17.206 for the first time.

 Viewed

June 28, 2025 @ 8:50 pm

Estimate viewed by 172.70.127.213 for the first time.

 Viewed

June 30, 2025 @ 2:30 am

Estimate viewed by 172.68.102.112 for the first time.

 Viewed

July 5, 2025 @ 12:42 pm

Estimate viewed by 172.69.17.207 for the first time.

 Viewed

July 31, 2025 @ 5:58 am

Estimate viewed by 172.69.134.31 for the first time.

 Viewed

August 5, 2025 @ 3:44 am

Estimate viewed by 172.70.179.180 for the first time.

 Viewed

August 15, 2025 @ 7:40 pm

Estimate viewed by 172.69.58.139 for the first time.

 Viewed

August 18, 2025 @ 9:30 am

Estimate viewed by 172.68.205.190 for the first time.

 Viewed

August 18, 2025 @ 3:44 pm

Estimate viewed by 172.71.178.48 for the first time.

 Viewed

August 19, 2025 @ 8:40 am

Estimate viewed by 172.70.130.19 for the first time.

 Viewed

August 19, 2025 @ 11:26 am

Estimate viewed by 172.70.100.157 for the first time.

 Viewed

August 20, 2025 @ 7:30 am

Estimate viewed by 141.101.99.111 for the first time.

 Viewed

August 22, 2025 @ 6:55 pm

Estimate viewed by 172.70.126.24 for the first time.

 Viewed

August 31, 2025 @ 8:14 am

Estimate viewed by 172.69.6.43 for the first time.

 Viewed

September 3, 2025 @ 9:44 pm

Estimate viewed by 172.69.17.186 for the first time.

 Viewed

September 4, 2025 @ 1:25 am

Estimate viewed by 162.158.108.84 for the first time.

 Viewed

September 4, 2025 @ 4:31 am

Estimate viewed by 172.68.164.13 for the first time.

 Viewed

September 5, 2025 @ 11:58 am

Estimate viewed by 104.23.225.81 for the first time.

-  **Viewed**
September 5, 2025 @ 11:58 am
Estimate viewed by 172.71.203.129 for the first time.
-  **Viewed**
September 9, 2025 @ 10:49 am
Estimate viewed by 108.162.246.76 for the first time.
-  **Viewed**
September 10, 2025 @ 7:57 am
Estimate viewed by 172.70.126.107 for the first time.
-  **Viewed**
September 10, 2025 @ 10:35 am
Estimate viewed by 141.101.99.9 for the first time.
-  **Viewed**
September 12, 2025 @ 2:50 am
Estimate viewed by 172.70.126.106 for the first time.
-  **Viewed**
September 18, 2025 @ 9:44 pm
Estimate viewed by 172.71.254.131 for the first time.
-  **Viewed**
October 30, 2025 @ 2:20 am
Estimate viewed by 172.71.255.126 for the first time.
-  **Viewed**
December 17, 2025 @ 5:39 am
Estimate viewed by 172.68.245.166 for the first time.
-  **Viewed**
December 18, 2025 @ 2:27 pm
Estimate viewed by 172.71.82.29 for the first time.
-  **Viewed**
December 20, 2025 @ 3:01 am
Estimate viewed by 172.70.42.239 for the first time.
-  **Viewed**
December 24, 2025 @ 5:55 am
Estimate viewed by 172.71.195.89 for the first time.
-  **Viewed**
January 15, 2026 @ 2:02 pm
Estimate viewed by 172.70.179.88 for the first time.

-  Viewed
February 3, 2026 @ 4:34 pm
Estimate viewed by 172.70.34.136 for the first time.
-  Viewed
February 6, 2026 @ 3:14 am
Estimate viewed by 104.23.239.144 for the first time.
-  Viewed
March 3, 2026 @ 9:00 am
Estimate viewed by 172.70.126.17 for the first time.
-  Viewed
March 3, 2026 @ 10:45 am
Estimate viewed by 172.71.254.254 for the first time.
-  Viewed
April 6, 2026 @ 5:39 pm
Estimate viewed by 104.22.17.144 for the first time.
-  Viewed
April 18, 2026 @ 5:57 pm
Estimate viewed by 172.71.218.155 for the first time.
-  Viewed
April 20, 2026 @ 10:35 am
Estimate viewed by 104.22.64.36 for the first time.
-  Viewed
April 25, 2026 @ 5:59 am
Estimate viewed by 104.22.17.145 for the first time.
-  Viewed
May 3, 2026 @ 12:52 pm
Estimate viewed by 172.69.7.16 for the first time.
-  Viewed
May 14, 2026 @ 2:23 am
Estimate viewed by 104.22.18.30 for the first time.
-  Viewed
May 14, 2026 @ 11:41 pm
Estimate viewed by 162.158.167.169 for the first time.
-  Viewed
May 23, 2026 @ 6:50 pm
Estimate viewed by 172.69.17.139 for the first time.

 Viewed

June 11, 2026 @ 2:18 am

Estimate viewed by 172.68.211.220 for the first time.



 Viewed

June 17, 2026 @ 2:53 pm

Estimate viewed by 172.69.7.140 for the first time.



 Viewed

June 22, 2026 @ 11:04 pm

Estimate viewed by 162.158.186.126 for the first time.

