

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:"ctlSignature",SignWidth:
"450",TransparentSign:"true",SignHeight:"300",leModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor:
"#FFFFFF", BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-
pro/bundles/sprout-invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-
invoices-pro/bundles/sprout-invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.",
ErrorMessage: "Please continue with a valid signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.",
SignzIndex: 1000, Visible: "true", forceMouseEvent: true, Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init();
$("#sign_doc").on('click', function(event) { event.preventDefault(); // scroll to signature $('html, body').animate({ scrollTop:
$("#ctlSignature_Container").offset().top }, 1000); }); $("#save_signature_via_ajax").on('click', function(event) { if (! ValidateSignature() ) { return; }
var sig_data = $("#ctlSignature_data").val(), sig_data_smooth = $("#ctlSignature_data_canvas").val(); $(this).after(si_js_object.inline_spinner);
$.post( si_js_object.ajax_url, { action: 'si_save_signature', invoice_id: 4199, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce:
si_js_object.security }, function( response ) { $('spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $("#sign_doc").hide();
$("#ctlSignature_toolbar").hide(); // show signature $("#si_signature_wrap").html( response.data.img ); // Add ability to pay $(
'stipe_checkout_button').show(); $('.square_checkout').show(); $('.button.status_change').show(); $('a.button.primary_button.purchase_button'
).show(); $('a.button.primary_button.payment_option').show(); // New Theme $("#paybar_inner.button.open).show(); // scroll to the top $('html,
body').animate({ scrollTop: $("#outer_doc_wrap").offset().top }, 500); } else { $("#save_signature_via_ajax").after(" + response.data.message + "); }
}); //> body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals {
page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; }
#doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button,
#doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border:
none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding:
10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; }
body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf }
body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-
color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; }
body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; }
jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf');
jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href",
"https://valleywidepro.com/estimate/5ed53c452986b7cc744f1a09ae3ffe47/"); jQuery(".button.primary_button.purchase_button").attr("href",
"https://valleywidepro.com/estimate/5ed53c452986b7cc744f1a09ae3ffe47/"); jQuery(".button.primary_button.payment_option").attr("href",
"https://valleywidepro.com/estimate/5ed53c452986b7cc744f1a09ae3ffe47/"); jQuery("#change_payment_amount").attr("href",
"https://valleywidepro.com/estimate/5ed53c452986b7cc744f1a09ae3ffe47/"); });
```

(4199) Foam Roof Replacement – 8773 E VIA DE DORADO

.button.status_change, a.button.primary_button.purchase_button, a.button.primary_button.payment_option { display: none; } .stipe_checkout_button { display: none; } .square_checkout { display: none; } .button.status_change[data-status-change=decline] { display: inline-block !important; }

[Decline Estimate](#)

[Signature Required](#)

[Print to PDF](#)

[Accept Estimate](#)

Richelle Davis
8778 E Via De Dorado
Scottsdale, AZ 85258
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US



Date

November 18, 2024



Estimate Number

4199



Estimate Due

December 18, 2024



Estimate Total

\$14,900.00

Service	Price	Amount
<ul style="list-style-type: none"> This applies to installing a new foam roof over the entire flat roof @ 33 sq's and the maintenance shed @ 2 sq's. Remove two layers of roofing from the entire flat roof and maintenance shed. Remove and replace up to (5) bad plywood sheets as needed throughout the roof. <i>Additional plywood sheets as needed would add \$85/sheet to the total.</i> Apply 1" foam over the entire flat roof. Remove and replace T-Tops from the foam roof. Install (1) 2x4 and (2) 2x2 skylights and from the roof. Seal all penetrations, haul away debris, and keep yard clean. Provide 5 year warranty against leaks over the entire new foam roof, @ 35 sq's (includes maint. shed). Annual Maintenance Package req'd after 5 years. <p>WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed in the TOTAL. 50% due at signing / 50% due upon completion.</p>	\$14,900	\$14,900
	Subtotal	\$0.00
	Total	\$14,900.00

To approve this estimate, 50% is due at signing, 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Phone: (877) 692-9762

Email: info@azroc.gov

Address: Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812

Website: www.azroc.gov

Please reference our license number ROC# 348219 when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

Thank you; we really appreciate your business! Please be sure to leave us a review upon completion of your project. Referrals are our lifeline, please tell your neighbors about Valleywide Pro Roofing!

Save Signature!

<https://valleywidepro.com> billing@valleywidepro.com



Updated

November 19, 2024 @ 12:50 am

Estimate updated by valleywide.



Updated

November 19, 2024 @ 12:51 am

Estimate updated by valleywide.



 Updated

November 19, 2024 @ 12:53 am

Estimate updated by valleywide.

 Viewed

November 19, 2024 @ 12:54 am

Estimate viewed by 172.69.59.8 for the first time.

 Viewed

November 19, 2024 @ 12:54 am

Estimate viewed by 172.69.7.61 for the first time.

 Viewed

November 19, 2024 @ 12:55 am

Estimate viewed by for the first time.

 Viewed

November 19, 2024 @ 12:55 am

Estimate viewed by (valleywide) for the first time.

 Viewed

November 19, 2024 @ 12:55 am

Estimate viewed by 172.70.214.3 for the first time.

 Viewed

November 19, 2024 @ 12:58 am

Estimate viewed by 172.69.34.63 for the first time.

 Viewed

November 19, 2024 @ 9:25 am

Estimate viewed by 172.70.206.57 for the first time.

 Viewed

February 11, 2025 @ 12:14 am

Estimate viewed by 172.71.255.67 for the first time.

 Viewed

February 14, 2025 @ 2:42 am

Estimate viewed by 172.70.179.142 for the first time.

 Viewed

February 18, 2025 @ 4:17 am

Estimate viewed by 172.70.43.7 for the first time.

 Viewed

February 18, 2025 @ 9:30 am

Estimate viewed by 172.70.174.98 for the first time.

 Viewed

February 18, 2025 @ 9:30 am

Estimate viewed by 172.69.17.67 for the first time.

 Viewed

February 23, 2025 @ 1:29 pm

Estimate viewed by 172.70.130.226 for the first time.

 Viewed

March 1, 2025 @ 6:02 pm

Estimate viewed by 108.162.226.230 for the first time.

 Viewed

March 16, 2025 @ 12:02 am

Estimate viewed by 172.68.164.18 for the first time.

 Viewed

April 5, 2025 @ 6:13 am

Estimate viewed by 172.70.206.51 for the first time.

 Viewed

May 29, 2025 @ 3:05 pm

Estimate viewed by 172.70.130.48 for the first time.

 Viewed

May 29, 2025 @ 3:05 pm

Estimate viewed by 108.162.216.120 for the first time.

 Viewed

June 3, 2025 @ 12:55 pm

Estimate viewed by 172.71.170.124 for the first time.

 Viewed

June 5, 2025 @ 3:12 am

Estimate viewed by 172.71.254.131 for the first time.

 Viewed

June 5, 2025 @ 3:13 am

Estimate viewed by 172.71.254.124 for the first time.

 Viewed

June 16, 2025 @ 9:13 pm

Estimate viewed by 172.70.142.234 for the first time.

 Viewed

July 1, 2025 @ 8:36 am

Estimate viewed by 162.158.155.18 for the first time.

 Viewed

August 17, 2025 @ 11:00 pm

Estimate viewed by 172.71.166.155 for the first time.

 Viewed

August 31, 2025 @ 4:18 am

Estimate viewed by 172.70.179.83 for the first time.

 Viewed

September 6, 2025 @ 3:49 am

Estimate viewed by 162.158.108.99 for the first time.

 Viewed

September 6, 2025 @ 7:25 pm

Estimate viewed by 172.68.26.151 for the first time.

 Viewed

September 10, 2025 @ 10:36 am

Estimate viewed by 141.101.99.9 for the first time.

 Viewed

September 12, 2025 @ 2:47 am

Estimate viewed by 172.70.179.194 for the first time.

 Viewed

September 17, 2025 @ 3:17 am

Estimate viewed by 172.70.39.34 for the first time.

 Viewed

September 18, 2025 @ 9:44 pm

Estimate viewed by 172.70.179.45 for the first time.

 Viewed

October 20, 2025 @ 12:07 pm

Estimate viewed by 172.70.135.16 for the first time.

 Viewed

October 30, 2025 @ 2:16 am

Estimate viewed by 172.69.7.44 for the first time.

 Viewed

December 1, 2025 @ 10:42 am

Estimate viewed by 104.23.213.81 for the first time.

 Viewed

December 5, 2025 @ 6:11 pm

Estimate viewed by 104.23.175.205 for the first time.

 Viewed

December 7, 2025 @ 5:57 am

Estimate viewed by 172.70.194.133 for the first time.

 Viewed

December 31, 2025 @ 5:00 am

Estimate viewed by 172.71.195.90 for the first time.

 Viewed

February 3, 2026 @ 11:56 am

Estimate viewed by 104.23.187.204 for the first time.

 Viewed

February 6, 2026 @ 3:13 am

Estimate viewed by 104.23.239.144 for the first time.

 Viewed

March 10, 2026 @ 1:33 pm

Estimate viewed by 172.70.93.16 for the first time.

 Viewed

March 21, 2026 @ 2:11 pm

Estimate viewed by 172.69.59.156 for the first time.

 Viewed

April 7, 2026 @ 11:32 am

Estimate viewed by 162.158.167.170 for the first time.

 Viewed

April 10, 2026 @ 6:14 pm

Estimate viewed by 104.23.195.87 for the first time.

 Viewed

April 18, 2026 @ 4:32 am

Estimate viewed by 162.159.98.90 for the first time.

 Viewed

April 25, 2026 @ 2:19 am

Estimate viewed by 172.70.126.103 for the first time.

 Viewed

April 28, 2026 @ 5:20 am

Estimate viewed by 162.158.178.46 for the first time.

 Viewed

April 28, 2026 @ 9:18 pm

Estimate viewed by 172.70.100.160 for the first time.

 Viewed
April 28, 2026 @ 10:13 pm

Estimate viewed by 172.68.34.172 for the first time.

 Viewed
June 18, 2026 @ 2:43 pm

Estimate viewed by 172.71.1146 for the first time.

 Viewed
June 22, 2026 @ 5:14 am

Estimate viewed by 172.70.34.136 for the first time.

 Viewed
June 22, 2026 @ 5:35 am

Estimate viewed by 172.71.255.2 for the first time.

 Viewed
June 22, 2026 @ 5:57 am

Estimate viewed by 172.68.35.153 for the first time.

 Viewed
June 22, 2026 @ 6:16 am

Estimate viewed by 172.70.174.187 for the first time.

 Viewed
June 22, 2026 @ 6:32 am

Estimate viewed by 108.162.216.149 for the first time.

 Viewed
June 22, 2026 @ 6:57 am

Estimate viewed by 104.22.14.92 for the first time.

 Viewed
June 22, 2026 @ 8:27 pm

Estimate viewed by 162.158.186.127 for the first time.

 Viewed
June 23, 2026 @ 9:23 pm

Estimate viewed by 172.69.17.138 for the first time.

 Viewed
June 24, 2026 @ 3:37 am

Estimate viewed by 104.23.211.90 for the first time.

