

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:"ctlSignature",SignWidth:
"450",TransparentSign:"true",SignHeight: "300",leModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor:
"#FFFFFF", BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-
pro/bundles/sprout-invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-
invoices-pro/bundles/sprout-invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.",
ErrorMessage: "Please continue with a valid signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.",
SignzIndex: 1000, Visible: "true", forceMouseEvent: true, Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init();
$("#sign_doc").on('click', function(event) { event.preventDefault(); // scroll to signature $('html, body').animate({ scrollTop:
$("#ctlSignature_Container").offset().top }, 1000); }); $("#save_signature_via_ajax").on('click', function(event) { if ( ! ValidateSignature() ) { return; }
var sig_data = $("#ctlSignature_data").val(), sig_data_smooth = $("#ctlSignature_data_canvas").val(); $(this).after(si_js_object.inline_spinner);
$.post( si_js_object.ajax_url, { action: 'si_save_signature', invoice_id: 753, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce:
si_js_object.security }, function( response ) { $('spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $("#sign_doc").hide();
$("#ctlSignature_toolbar").hide(); // show signature $("#si_signature_wrap").html( response.data.img ); // Add ability to pay $(
'stipe_checkout_button').show(); $('square_checkout').show(); $('button.status_change').show(); $('a.button.primary_button.purchase_button'
).show(); $('a.button.primary_button.payment_option').show(); // New Theme $("#paybar_inner.button.open").show(); // scroll to the top $('html,
body').animate({ scrollTop: $("#outer_doc_wrap").offset().top }, 500); } else { $("#save_signature_via_ajax").after(" + response.data.message + "); }
}); //]]> body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals {
page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; }
#doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button,
#doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border:
none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding:
10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; }
body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf }
body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-
color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; }
body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; }
jQuery(document).ready(function() { jQuery("#invoice.sa_invoice-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf');
jQuery("#estimate.sa_estimate-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href",
"https://valleywidepro.com/estimate/805220083ec13cb6a3730191e413d128/"); jQuery(".button.primary_button.purchase_button").attr("href",
"https://valleywidepro.com/estimate/805220083ec13cb6a3730191e413d128/"); jQuery(".button.primary_button.payment_option").attr("href",
"https://valleywidepro.com/estimate/805220083ec13cb6a3730191e413d128/"); jQuery("#change_payment_amount").attr("href",
"https://valleywidepro.com/estimate/805220083ec13cb6a3730191e413d128/"); });
```

753

.button.status_change, a.button.primary_button.purchase_button, a.button.primary_button.payment_option { display: none; } .stipe_checkout_button { display: none; } .square_checkout { display: none; } button.status_change[data-status-change=decline] { display: inline-block !important; }

Decline Estimate

Signature Required

Print to PDF

Accept Estimate

Juan Mora
10327 W Foothill Drive
Peoria, AZ 85383
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US



Date

October 21, 2023



Estimate Number

753



Estimate Due

November 20, 2023

Estimate Total

\$6,900.00

Task	Rate	Qty	%	Amount
<p>ESTIMATE SPECS FOR Tile Roof Repair + Maintenance</p> <ul style="list-style-type: none"> —This proposal applies to repairing the tile roof on the west half of 2nd story @ 10 sq's. —Remove tile from repair area then set aside, re-install after repair (unless broken—then replace). —Remove felt and remove and replace battens from the repair area. —Remove and replace {plywood_sheets} sheets of bad plywood (as needed) throughout the repair area. Additional plywood billed at \$80/sheet. —Install {underlayment_layers} layer(s) of new #40 Underlayment over the repair area. —Install new 3 inch x 3 inch drip edge around the perimeter of the repair area. —Install new L metals, roof jacks, T-Top air vents, and O'Hagin vents throughout the roof. —Install new ridge and hip enclosures as needed throughout the roof. —Install new bird stops as needed throughout the roof. Remove and replace broken tiles from the remaining of the roof as needed. —Seal all penetrations, haul away debris and keep yard clean. —Provide 5 year warranty against leaks over the repair area only , @ 10 sq's. <p>ESTIMATED COMPLETION: 1-2 Days</p> <p>WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed below. Tax is included in price.</p>	\$6,900	1	0%	\$6,900

Subtotal

\$0.00

Total

\$6,900.00

Thank you; we really appreciate your business! Please be sure to leave us a review upon completion of your project – we reward any reviews with a gift card. Referrals are our lifeline, please tell your neighbors about Valleywide!

ACCEPTANCE OF PROPOSAL: These prices, specifications, and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified.

To approve this estimate, 50% is due prior to the beginning of the project.

Save Signature!

<https://valleywidepro.com> billing@valleywidepro.com



 Updated

October 21, 2023 @ 11:38 am

Estimate updated by Carlos Mendivil.

 Updated

October 21, 2023 @ 11:38 am

Estimate updated by Carlos Mendivil.

 Viewed

October 21, 2023 @ 11:38 am

Estimate viewed by Carlos Mendivil (carlos) for the first time.

 Viewed

October 24, 2023 @ 4:38 pm

Estimate viewed by 162.158.186.157 for the first time.

 Viewed

October 24, 2023 @ 4:38 pm

Estimate viewed by 172.71.222.157 for the first time.

 Viewed

October 24, 2023 @ 4:39 pm

Estimate viewed by 172.71.254.73 for the first time.

 Viewed

October 24, 2023 @ 5:34 pm

Estimate viewed by 172.70.175.180 for the first time.

 Viewed

October 24, 2023 @ 5:34 pm

Estimate viewed by 172.70.100.111 for the first time.

 Viewed

January 13, 2024 @ 6:11 pm

Estimate viewed by for the first time.

 Viewed

March 24, 2024 @ 6:25 am

Estimate viewed by 172.68.138.201 for the first time.

 Viewed

July 11, 2024 @ 2:02 pm

Estimate viewed by 172.70.55.49 for the first time.

 Viewed

February 11, 2025 @ 12:12 am

Estimate viewed by 108.162.216.180 for the first time.

Estimate viewed by 172.69.17.211 for the first time.

 Viewed

February 14, 2025 @ 2:41 am

Estimate viewed by 172.70.178.24 for the first time.

 Viewed

February 23, 2025 @ 1:24 pm

 Viewed

March 1, 2025 @ 1:19 pm

Estimate viewed by 162.158.106.21 for the first time.

 Viewed

April 13, 2025 @ 10:00 pm

Estimate viewed by 172.71.8.10 for the first time.

 Viewed

May 31, 2025 @ 10:18 pm

Estimate viewed by 172.71.254.100 for the first time.

 Viewed

June 3, 2025 @ 12:33 pm

Estimate viewed by 172.71.166.253 for the first time.

 Viewed

June 4, 2025 @ 5:18 am

Estimate viewed by 108.162.216.77 for the first time.

 Viewed

June 5, 2025 @ 3:13 am

Estimate viewed by 172.69.17.151 for the first time.

 Viewed

June 5, 2025 @ 12:01 pm

Estimate viewed by 172.71.254.17 for the first time.

 Viewed

June 10, 2025 @ 5:04 am

Estimate viewed by 172.70.179.72 for the first time.

 Viewed

June 11, 2025 @ 12:16 pm

Estimate viewed by 172.70.100.55 for the first time.

 Viewed

June 30, 2025 @ 2:40 am

Estimate viewed by 162.158.106.208 for the first time.

 Viewed

July 31, 2025 @ 6:09 am

Estimate viewed by 172.68.26.150 for the first time.

 Viewed

August 15, 2025 @ 3:51 am

Estimate viewed by 172.69.58.97 for the first time.

 Viewed

August 18, 2025 @ 7:00 am

Estimate viewed by 172.68.7.106 for the first time.

 Viewed

August 19, 2025 @ 2:39 am

Estimate viewed by 172.69.6.144 for the first time.

 Viewed

August 19, 2025 @ 3:40 pm

Estimate viewed by 172.69.17.65 for the first time.

 Viewed

August 22, 2025 @ 7:09 pm

Estimate viewed by 172.69.194.171 for the first time.

 Viewed

September 5, 2025 @ 10:34 am

Estimate viewed by 162.158.86.98 for the first time.

 Viewed

September 6, 2025 @ 12:03 am

Estimate viewed by 162.158.88.77 for the first time.

 Viewed

September 7, 2025 @ 8:45 am

Estimate viewed by 108.162.216.195 for the first time.

 Viewed

September 9, 2025 @ 10:55 am

Estimate viewed by 141.101.99.9 for the first time.

 Viewed

September 10, 2025 @ 7:54 am

Estimate viewed by 172.70.126.106 for the first time.

 Viewed

September 12, 2025 @ 2:49 am

Estimate viewed by 172.69.59.32 for the first time.

 Viewed

September 18, 2025 @ 9:45 pm

Estimate viewed by 172.69.7.154 for the first time.

 Viewed

October 19, 2025 @ 9:40 pm

Estimate viewed by 162.158.163.122 for the first time.

 Viewed

October 30, 2025 @ 11:03 am

Estimate viewed by 172.68.164.13 for the first time.

 Viewed

October 30, 2025 @ 5:57 pm

Estimate viewed by 172.70.188.46 for the first time.

 Viewed

October 30, 2025 @ 9:49 pm

Estimate viewed by 104.23.175.138 for the first time.

 Viewed

November 1, 2025 @ 1:49 am

Estimate viewed by 172.71.82.29 for the first time.

 Viewed

November 1, 2025 @ 8:44 pm

Estimate viewed by 104.23.175.26 for the first time.

 Viewed

November 2, 2025 @ 1:43 am

Estimate viewed by 162.158.88.76 for the first time.

 Viewed

November 2, 2025 @ 6:59 am

Estimate viewed by 162.158.163.125 for the first time.

 Viewed

November 2, 2025 @ 10:23 am

Estimate viewed by 108.162.226.172 for the first time.

 Viewed

November 3, 2025 @ 3:34 am

Estimate viewed by 172.69.176.62 for the first time.

 Viewed

November 3, 2025 @ 10:39 am

Estimate viewed by 172.70.92.183 for the first time.

 Viewed

November 4, 2025 @ 10:23 am

Estimate viewed by 172.71.124.172 for the first time.

 Viewed

November 5, 2025 @ 4:43 am

Estimate viewed by 172.71.152.30 for the first time.

 Viewed

November 6, 2025 @ 5:21 am

Estimate viewed by 162.158.106.155 for the first time.

 Viewed

November 6, 2025 @ 10:02 am

Estimate viewed by 172.68.164.12 for the first time.

 Viewed

November 7, 2025 @ 6:58 pm

Estimate viewed by 172.64.217.219 for the first time.

 Viewed

November 9, 2025 @ 10:30 pm

Estimate viewed by 104.23.175.219 for the first time.

 Viewed

November 10, 2025 @ 12:32 pm

Estimate viewed by 172.70.208.25 for the first time.

 Viewed

November 12, 2025 @ 10:39 am

Estimate viewed by 162.158.170.238 for the first time.

 Viewed

November 14, 2025 @ 2:13 am

Estimate viewed by 172.70.208.24 for the first time.

 Viewed

December 17, 2025 @ 4:55 am

Estimate viewed by 172.70.174.245 for the first time.

 Viewed

December 20, 2025 @ 8:47 am

Estimate viewed by 172.71.223.6 for the first time.

 Viewed

January 14, 2026 @ 10:03 am

Estimate viewed by 172.70.126.40 for the first time.

 Viewed

January 15, 2026 @ 12:43 pm

Estimate viewed by 172.69.17.66 for the first time.

 Viewed

January 27, 2026 @ 10:45 pm

Estimate viewed by 162.158.187.190 for the first time.



 Viewed

February 3, 2026 @ 10:57 pm

Estimate viewed by 104.23.213.80 for the first time.



 Viewed

February 6, 2026 @ 3:14 am

Estimate viewed by 104.23.239.144 for the first time.



 Viewed

March 17, 2026 @ 11:40 pm

Estimate viewed by 172.70.126.80 for the first time.



 Viewed

March 18, 2026 @ 1:35 am

Estimate viewed by 104.22.62.13 for the first time.



 Viewed

March 20, 2026 @ 2:43 am

Estimate viewed by 172.69.59.140 for the first time.



 Viewed

April 11, 2026 @ 10:55 am

Estimate viewed by 104.22.62.130 for the first time.



 Viewed

April 12, 2026 @ 4:57 am

Estimate viewed by 172.70.100.159 for the first time.



 Viewed

April 25, 2026 @ 5:45 am

Estimate viewed by 172.71.155.171 for the first time.



 Viewed

April 29, 2026 @ 8:44 am

Estimate viewed by 172.68.159.215 for the first time.



 Viewed

June 18, 2026 @ 7:07 pm

Estimate viewed by 172.69.7.140 for the first time.

