

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:"ctlSignature",SignWidth:
'450",TransparentSign:"true",SignHeight: "300",IsModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor:
"#FFFFFF", BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-
pro/bundles/sprout-invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-
invoices-pro/bundles/sprout-invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.",
ErrorMessage: "Please continue with a valid signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.",
SignzIndex: 1000, Visible: "true", forceMouseEvent: true, Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init();
$("#sign_doc").on('click', function(event) { event.preventDefault(); // scroll to signature $('html, body').animate({ scrollTop:
$("#ctlSignature_Container").offset().top }, 1000); }); $("#save_signature_via_ajax").on('click', function(event) { if ( ! ValidateSignature() ) { return; }
var sig_data = $("#ctlSignature_data").val(), sig_data_smooth = $("#ctlSignature_data_canvas").val(); $(this).after(si_js_object.inline_spinner);
$.post( si_js_object.ajax_url, { action: 'si_save_signature', invoice_id: 753, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce:
si_js_object.security }, function( response ) { $('#spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $('#sign_doc').hide();
$("#ctlSignature_toolbar").hide(); // show signature $('#si_signature_wrap').html( response.data.img ); // Add ability to pay $(
'stipe_checkout_button').show(); $('#square_checkout').show(); $('#button.status_change').show(); $('#a.button.primary_button.purchase_button'
).show(); $('#a.button.primary_button.payment_option').show(); // New Theme $('#paybar.inner.button.open').show(); // scroll to the top $('html,
body').animate({ scrollTop: $("#outer_doc_wrap").offset().top }, 500); } else { $("#save_signature_via_ajax").after(" + response.data.message + "); }
}); //> body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals {
page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; }
#doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button,
#doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border:
none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding:
10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; }
body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf }
body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-
color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; }
body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; }
jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf');
jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href",
"https://valleywidepro.com/estimate/805220083ec13cb6a3730191e413d128/"); jQuery(".button.primary_button.purchase_button").attr("href",
"https://valleywidepro.com/estimate/805220083ec13cb6a3730191e413d128/"); jQuery(".button.primary_button.payment_option").attr("href",
"https://valleywidepro.com/estimate/805220083ec13cb6a3730191e413d128/"); jQuery("#change_payment_amount").attr("href",
"https://valleywidepro.com/estimate/805220083ec13cb6a3730191e413d128/"); });
```

## 753

.button.status\_change, a.button.primary\_button.purchase\_button, a.button.primary\_button.payment\_option { display: none; } .stipe\_checkout\_button { display: none; } .square\_checkout { display: none; } button.status\_change[data-status-change=decline] { display: inline-block !important; }

**Decline Estimate**

**Signature Required**

**Print to PDF**

**Accept Estimate**

**Juan Mora**  
10327 W Foothill Drive  
Peoria, AZ 85383  
US



**Valleywide Pro Roofing** 4022 W  
Palo Verde Dr  
Phoenix, AZ 85019  
US



Date

October 21, 2023



Estimate Number

753



Estimate Due

November 20, 2023



Estimate Total

\$6,900.00

| Task  | Rate    | Qty | %  | Amount  |
|---|---------|-----|---|---------|
| <p><b>ESTIMATE SPECS FOR Tile Roof Repair + Maintenance</b></p> <ul style="list-style-type: none"> <li>—This proposal applies to repairing the tile roof on the west half of 2nd story @ 10 sq's.</li> <li>—Remove tile from repair area then set aside, re-install after repair (unless broken—then replace).</li> <li>—Remove felt and remove and replace battens from the repair area.</li> <li>—Remove and replace {plywood_sheets} sheets of bad plywood (as needed) throughout the repair area. Additional plywood billed at \$80/sheet.</li> <li>—Install {underlayment_layers} layer(s) of new #40 Underlayment over the repair area.</li> <li>—Install new 3 inch x 3 inch drip edge around the perimeter of the repair area.</li> <li>—Install new L metals, roof jacks, T-Top air vents, and O'Hagin vents throughout the roof.</li> <li>—Install new ridge and hip enclosures as needed throughout the roof.</li> <li>—Install new bird stops as needed throughout the roof.</li> <li>Remove and replace broken tiles from the remaining of the roof as needed.</li> <li>—Seal all penetrations, haul away debris and keep yard clean.</li> <li>—Provide 5 year warranty against leaks over the repair area only , @ 10 sq's.</li> </ul> <p>ESTIMATED COMPLETION: 1-2 Days</p> <p>WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed below. Tax is included in price.</p> | \$6,900 | 1   | 0%  | \$6,900 |

Subtotal

\$0.00

Total

\$6,900.00

Thank you; we really appreciate your business! Please be sure to leave us a review upon completion of your project – we reward any reviews with a gift card. Referrals are our lifeline, please tell your neighbors about Valleywide!

ACCEPTANCE OF PROPOSAL: These prices, specifications, and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified.

---

To approve this estimate, 50% is due prior to the beginning of the project.

**Save Signature!**

<https://valleywidepro.com> [billing@valleywidepro.com](mailto:billing@valleywidepro.com)



 Updated

October 21, 2023 @ 11:38 am

Estimate updated by Carlos Mendivil.

 Updated

October 21, 2023 @ 11:38 am

Estimate updated by Carlos Mendivil.

 Viewed

October 21, 2023 @ 11:38 am

Estimate viewed by Carlos Mendivil (carlos) for the first time.

 Viewed

October 24, 2023 @ 4:38 pm

Estimate viewed by 162.158.186.157 for the first time.

 Viewed

October 24, 2023 @ 4:38 pm

Estimate viewed by 172.71.222.157 for the first time.

 Viewed

October 24, 2023 @ 4:39 pm

Estimate viewed by 172.71.254.73 for the first time.

 Viewed

October 24, 2023 @ 5:34 pm

Estimate viewed by 172.70.175.180 for the first time.

 Viewed

October 24, 2023 @ 5:34 pm

Estimate viewed by 172.70.100.111 for the first time.

 Viewed

January 13, 2024 @ 6:11 pm

Estimate viewed by for the first time.

 Viewed

March 24, 2024 @ 6:25 am

Estimate viewed by 172.68.138.201 for the first time.

 Viewed

July 11, 2024 @ 2:02 pm

Estimate viewed by 172.70.55.49 for the first time.

 Viewed

February 11, 2025 @ 12:12 am

Estimate viewed by 108.162.216.180 for the first time.

Estimate viewed by 172.69.17.211 for the first time.

 Viewed

February 14, 2025 @ 2:41 am

Estimate viewed by 172.70.178.24 for the first time.

 Viewed

February 23, 2025 @ 1:24 pm

 Viewed

March 1, 2025 @ 1:19 pm

Estimate viewed by 162.158.106.21 for the first time.

 Viewed

April 13, 2025 @ 10:00 pm

Estimate viewed by 172.71.8.10 for the first time.

 Viewed

May 31, 2025 @ 10:18 pm

Estimate viewed by 172.71.254.100 for the first time.

 Viewed

June 3, 2025 @ 12:33 pm

Estimate viewed by 172.71.166.253 for the first time.

 Viewed

June 4, 2025 @ 5:18 am

Estimate viewed by 108.162.216.77 for the first time.

 Viewed

June 5, 2025 @ 3:13 am

Estimate viewed by 172.69.17.151 for the first time.

 Viewed

June 5, 2025 @ 12:01 pm

Estimate viewed by 172.71.254.17 for the first time.

 Viewed

June 10, 2025 @ 5:04 am

Estimate viewed by 172.70.179.72 for the first time.

 Viewed

June 11, 2025 @ 12:16 pm

Estimate viewed by 172.70.100.55 for the first time.

 Viewed

June 30, 2025 @ 2:40 am

Estimate viewed by 162.158.106.208 for the first time.

 Viewed

July 31, 2025 @ 6:09 am

Estimate viewed by 172.68.26.150 for the first time.

 Viewed

August 15, 2025 @ 3:51 am

Estimate viewed by 172.69.58.97 for the first time.

 Viewed

August 18, 2025 @ 7:00 am

Estimate viewed by 172.68.7.106 for the first time.

 Viewed

August 19, 2025 @ 2:39 am

Estimate viewed by 172.69.6.144 for the first time.

 Viewed

August 19, 2025 @ 3:40 pm

Estimate viewed by 172.69.17.65 for the first time.

 Viewed

August 22, 2025 @ 7:09 pm

Estimate viewed by 172.69.194.171 for the first time.

 Viewed

September 5, 2025 @ 10:34 am

Estimate viewed by 162.158.86.98 for the first time.

 Viewed

September 6, 2025 @ 12:03 am

Estimate viewed by 162.158.88.77 for the first time.

 Viewed

September 7, 2025 @ 8:45 am

Estimate viewed by 108.162.216.195 for the first time.

 Viewed

September 9, 2025 @ 10:55 am

Estimate viewed by 141.101.99.9 for the first time.

 Viewed

September 10, 2025 @ 7:54 am

Estimate viewed by 172.70.126.106 for the first time.

 Viewed

September 12, 2025 @ 2:49 am

Estimate viewed by 172.69.59.32 for the first time.

 Viewed

September 18, 2025 @ 9:45 pm

Estimate viewed by 172.69.7.154 for the first time.

 Viewed

October 19, 2025 @ 9:40 pm

Estimate viewed by 162.158.163.122 for the first time.

 Viewed

October 30, 2025 @ 11:03 am

Estimate viewed by 172.68.164.13 for the first time.

 Viewed

October 30, 2025 @ 5:57 pm

Estimate viewed by 172.70.188.46 for the first time.

 Viewed

October 30, 2025 @ 9:49 pm

Estimate viewed by 104.23.175.138 for the first time.

 Viewed

November 1, 2025 @ 1:49 am

Estimate viewed by 172.71.82.29 for the first time.

 Viewed

November 1, 2025 @ 8:44 pm

Estimate viewed by 104.23.175.26 for the first time.

 Viewed

November 2, 2025 @ 1:43 am

Estimate viewed by 162.158.88.76 for the first time.

 Viewed

November 2, 2025 @ 6:59 am

Estimate viewed by 162.158.163.125 for the first time.

 Viewed

November 2, 2025 @ 10:23 am

Estimate viewed by 108.162.226.172 for the first time.

 Viewed

November 3, 2025 @ 3:34 am

Estimate viewed by 172.69.176.62 for the first time.

 Viewed

November 3, 2025 @ 10:39 am

Estimate viewed by 172.70.92.183 for the first time.

 Viewed

November 4, 2025 @ 10:23 am

Estimate viewed by 172.71.124.172 for the first time.

 Viewed

November 5, 2025 @ 4:43 am

Estimate viewed by 172.71.152.30 for the first time.

 Viewed

November 6, 2025 @ 5:21 am

Estimate viewed by 162.158.106.155 for the first time.

 Viewed

November 6, 2025 @ 10:02 am

Estimate viewed by 172.68.164.12 for the first time.

 Viewed

November 7, 2025 @ 6:58 pm

Estimate viewed by 172.64.217.219 for the first time.

 Viewed

November 9, 2025 @ 10:30 pm

Estimate viewed by 104.23.175.219 for the first time.

 Viewed

November 10, 2025 @ 12:32 pm

Estimate viewed by 172.70.208.25 for the first time.

 Viewed

November 12, 2025 @ 10:39 am

Estimate viewed by 162.158.170.238 for the first time.

 Viewed

November 14, 2025 @ 2:13 am

Estimate viewed by 172.70.208.24 for the first time.

 Viewed

December 17, 2025 @ 4:55 am

Estimate viewed by 172.70.174.245 for the first time.

 Viewed

December 20, 2025 @ 8:47 am

Estimate viewed by 172.71.223.6 for the first time.

 Viewed

January 14, 2026 @ 10:03 am

Estimate viewed by 172.70.126.40 for the first time.

 Viewed

January 15, 2026 @ 12:43 pm

Estimate viewed by 172.69.17.66 for the first time.

 Viewed

January 27, 2026 @ 10:45 pm

Estimate viewed by 162.158.187.190 for the first time.

 Viewed

February 3, 2026 @ 10:57 pm

Estimate viewed by 104.23.213.80 for the first time.

 Viewed

February 6, 2026 @ 3:14 am

Estimate viewed by 104.23.239.144 for the first time.

 Viewed

March 17, 2026 @ 11:40 pm

Estimate viewed by 172.70.126.80 for the first time.

 Viewed

March 18, 2026 @ 1:35 am

Estimate viewed by 104.22.62.13 for the first time.

 Viewed

March 20, 2026 @ 2:43 am

Estimate viewed by 172.69.59.140 for the first time.

 Viewed

April 11, 2026 @ 10:55 am

Estimate viewed by 104.22.62.130 for the first time.

 Viewed

April 12, 2026 @ 4:57 am

Estimate viewed by 172.70.100.159 for the first time.

 Viewed

April 25, 2026 @ 5:45 am

Estimate viewed by 172.71.155.171 for the first time.

 Viewed

April 29, 2026 @ 8:44 am

Estimate viewed by 172.68.159.215 for the first time.

 Viewed

June 18, 2026 @ 7:07 pm

Estimate viewed by 172.69.7.140 for the first time.

 Viewed

June 27, 2026 @ 2:53 am

Estimate viewed by 108.162.216.148 for the first time.



