

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:"ctlSignature",SignWidth:
"450",TransparentSign:"true",SignHeight:"300",IsModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor:
"#FFFFFF", BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-
pro/bundles/sprout-invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-
invoices-pro/bundles/sprout-invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.",
ErrorMessage: "Please continue with a valid signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.",
SignzIndex: 1000, Visible: "true", forceMouseEvent: true, Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init();
$("#sign_doc").on('click', function(event) { event.preventDefault(); // scroll to signature $('html, body').animate({ scrollTop:
$("#ctlSignature_Container").offset().top }, 1000); }); $("#save_signature_via_ajax").on('click', function(event) { if ( ! ValidateSignature() ) { return; }
var sig_data = $("#ctlSignature_data").val(), sig_data_smooth = $("#ctlSignature_data_canvas").val(); $(this).after(si_js_object.inline_spinner);
$.post( si_js_object.ajax_url, { action: 'si_save_signature', invoice_id: 10362, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce:
si_js_object.security }, function( response ) { $('spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $('#sign_doc').hide();
$('#ctlSignature_toolbar').hide(); // show signature $('#si_signature_wrap').html( response.data.img ); // Add ability to pay $(
'stipe_checkout_button').show(); $('#square_checkout').show(); $('#button.status_change').show(); $('#a.button.primary_button.purchase_button'
).show(); $('#a.button.primary_button.payment_option').show(); // New Theme $('#paybar.inner.button.open').show(); // scroll to the top $('html,
body').animate({ scrollTop: $('#outer_doc_wrap').offset().top }, 500); } else { $('#save_signature_via_ajax').after(" + response.data.message + "); }
}); //> body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals {
page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; }
#doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button,
#doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border:
none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding:
10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; }
body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf }
body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-
color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; }
body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; }
jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf');
jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href",
"https://valleywidepro.com/estimate/b17c7c78490f862c9572c61d29e851fc/"); jQuery(".button.primary_button.purchase_button").attr("href",
"https://valleywidepro.com/estimate/b17c7c78490f862c9572c61d29e851fc/"); jQuery(".button.primary_button.payment_option").attr("href",
"https://valleywidepro.com/estimate/b17c7c78490f862c9572c61d29e851fc/"); jQuery("#change_payment_amount").attr("href",
"https://valleywidepro.com/estimate/b17c7c78490f862c9572c61d29e851fc/"); });
```

(10362) TILE REPAIR – 14217 N WESTMINSTER PL

.button.status_change, a.button.primary_button.purchase_button, a.button.primary_button.payment_option { display: none; } .stipe_checkout_button { display: none; } .square_checkout { display: none; } .button.status_change[data-status-change=decline] { display: inline-block !important; }

[Decline Estimate](#)

[Signature Required](#)

[Print to PDF](#)

[Accept Estimate](#)

Susan Dempster (WESTMINSTER)
14217 N WESTMINSTER PL
FOUNTAIN HILLS, AZ 85268
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US



Date

November 11, 2025



Estimate Number

10362



Estimate Due

December 11, 2025

Estimate Total

\$950.00

Service	Price	Amount
<ul style="list-style-type: none"> • This repair includes tile roofing repair around chimney and flashing (match tile color as close as possible) • Remove and replace any bad sheets of plywood – any sheets replaced will add \$85/sheet to the total • Remove tile in repair area and set aside • Install new Tile Seal Underlayment to repair area • Re-install tiles • All mortar joints will be touched up as needed • Secure slipped tiles as needed • Seal all penetrations • Clean up debris <p>Provide 2 YEAR WARRANTY for workmanship against leaks on the repaired area.</p> <p>For questions, please contact your estimator – thank you!</p>	\$950	\$950

	Subtotal	\$0.00
	Total	\$950.00

Thank you; we really appreciate your business! Let us know if you have any questions about your estimate.

50% is due prior to the beginning of the project. 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, LLC, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Please reference our license number [ROC# 348219](#) when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

Warranty Statement for Roof Replacement Options

Thank you for choosing Valleywide Pro Roofing, LLC for your roofing needs. We are committed to providing high-quality materials and professional installation to ensure the longevity and performance of your new roof. To maximize the lifespan of your roof and maintain warranty coverage, the following warranty terms and conditions apply:

1. Warranty Coverage

All roof replacement options come with a comprehensive warranty that includes:

Underlayment Warranty: Coverage as per the manufacturer's warranty, ranging from 10 to 50 years depending on the underlayment type selected.

Tile Warranty: Coverage as per the manufacturer's warranty, ranging from 30 years to a lifetime, depending on the type of tile selected (standard concrete, premium concrete, or clay tiles).

2. Maintenance Requirements

To maintain the validity of the warranty beyond the initial 15/20/30 years, an **annual maintenance package** is required. This package is designed to ensure your roof remains in optimal condition and any potential issues are addressed promptly.

Annual Maintenance Package Cost: \$299/year.

Discounted Maintenance Plan: Customers have the option to pre-pay for maintenance in 5-year bundles at a discounted rate. See below for discounts.

Discounted Rates:

5-Year Maintenance Bundle: \$1,345 (a savings of \$150 compared to annual payments).

3. Manufacturer Warranty Claims

While Valleywide Pro Roofing, LLC provides a workmanship warranty on the installation and materials used, any claims related to the manufacturer's warranties (underlayment and tiles) must be processed directly through the manufacturer. Our team is available to assist you in facilitating these claims to ensure a smooth and efficient process.

4. Terms and Conditions

Warranty Activation: The warranty will become effective on the date of completion of the roof installation.

Maintenance Schedule: The annual maintenance package is mandatory after the initial 5-year period to continue the coverage. Failure to comply with the annual maintenance schedule may void the warranty.

Coverage Exclusions: The warranty does not cover damage caused by natural disasters, improper use, or modifications made to the roof after installation without prior consultation with Valleywide Pro Roofing, LLC. The warranty does not cover any work performed by other roofing contractors or companies not associated with Valleywide Pro Roofing, LLC.


Warranty Transfer: The warranty is transferable to a new homeowner upon the sale of the property, provided that all maintenance requirements have been met. A **one-time transfer fee of \$250** is required to transfer the warranty to the new homeowner.

We appreciate your business and are dedicated to providing you with a roof that offers protection and peace of mind for years to come. If you have any questions regarding the warranty or maintenance packages, please do not hesitate to contact us.

Save Signature!

<https://valleywidepro.com> billing@valleywidepro.com



 **Updated**
November 11, 2025 @ 2:11 am

Estimate updated by valleywide.

 **Updated**
November 11, 2025 @ 2:12 am

Estimate updated by valleywide.

 **Viewed**
November 11, 2025 @ 2:13 am

Estimate viewed by (valleywide) for the first time.

Estimate viewed by for the first time.

 Viewed

November 11, 2025 @ 2:13 am

Estimate viewed by Susan Dempster (susan.dempster@azmoves.com) for the first time.

 Viewed

November 11, 2025 @ 1:01 pm

 Status Update

November 11, 2025 @ 1:02 pm

Status changed: Pending to **Declined**.

 Viewed

November 11, 2025 @ 9:22 pm

Estimate viewed by 172.69.74.252 for the first time.

 Viewed

November 11, 2025 @ 9:25 pm

Estimate viewed by 104.23.195.80 for the first time.

 Viewed

November 11, 2025 @ 10:38 pm

Estimate viewed by Carlos Mendivil (carlos) for the first time.

 Updated

November 11, 2025 @ 10:39 pm

Estimate updated by Carlos Mendivil.

 Updated

November 11, 2025 @ 10:39 pm

Estimate updated by Carlos Mendivil.

 Updated

November 11, 2025 @ 10:39 pm

Estimate updated by Carlos Mendivil.

 Updated

November 11, 2025 @ 10:40 pm

Estimate updated by Carlos Mendivil.

 Updated

November 11, 2025 @ 10:41 pm

Estimate updated by Carlos Mendivil.

 Viewed

November 11, 2025 @ 10:45 pm

Estimate viewed by 172.70.126.17 for the first time.

 Viewed

November 11, 2025 @ 10:51 pm

Estimate viewed by 172.71.155.50 for the first time.

-  **Viewed**
November 11, 2025 @ 10:51 pm
Estimate viewed by 172.71.191.92 for the first time.
-  **Viewed**
November 11, 2025 @ 10:51 pm
Estimate viewed by 162.158.78.49 for the first time.
-  **Viewed**
November 13, 2025 @ 12:51 pm
Estimate viewed by 172.71.203.128 for the first time.
-  **Viewed**
November 13, 2025 @ 12:51 pm
Estimate viewed by 172.68.245.166 for the first time.
-  **Viewed**
November 13, 2025 @ 12:52 pm
Estimate viewed by 172.70.35.33 for the first time.
-  **Viewed**
November 13, 2025 @ 12:52 pm
Estimate viewed by 172.71.120.33 for the first time.
-  **Viewed**
November 13, 2025 @ 1:03 pm
Estimate viewed by 104.23.211.90 for the first time.
-  **Viewed**
November 13, 2025 @ 1:04 pm
Estimate viewed by 172.68.7.106 for the first time.
-  **Viewed**
November 13, 2025 @ 1:04 pm
Estimate viewed by 172.70.50.39 for the first time.
-  **Viewed**
November 15, 2025 @ 7:38 am
Estimate viewed by 162.158.91.129 for the first time.
-  **Viewed**
November 28, 2025 @ 6:45 pm
Estimate viewed by 104.23.190.108 for the first time.
-  **Viewed**
November 28, 2025 @ 6:45 pm
Estimate viewed by 172.71.222.70 for the first time.

 Viewed
November 28, 2025 @ 6:45 pm

Estimate viewed by 172.71.120.20 for the first time.

 Viewed
November 28, 2025 @ 6:45 pm

Estimate viewed by 162.158.79.111 for the first time.

 Viewed
November 28, 2025 @ 6:45 pm

Estimate viewed by 172.70.135.16 for the first time.

 Viewed
December 12, 2025 @ 2:16 pm

Estimate viewed by 172.69.176.63 for the first time.

 Viewed
December 23, 2025 @ 10:14 am

Estimate viewed by 172.71.255.2 for the first time.

 Viewed
December 23, 2025 @ 10:14 am

Estimate viewed by 172.70.130.220 for the first time.

 Viewed
December 24, 2025 @ 12:31 am

Estimate viewed by 172.71.222.37 for the first time.

 Viewed
January 5, 2026 @ 5:41 pm

Estimate viewed by 162.158.162.107 for the first time.

 Viewed
February 3, 2026 @ 6:07 pm

Estimate viewed by 172.68.245.167 for the first time.

 Viewed
February 6, 2026 @ 3:10 am

Estimate viewed by 172.71.148.37 for the first time.

 Viewed
March 10, 2026 @ 4:59 am

Estimate viewed by 172.69.17.139 for the first time.

 Viewed
March 13, 2026 @ 6:12 pm

Estimate viewed by 104.22.196 for the first time.

 Viewed

March 13, 2026 @ 6:12 pm

Estimate viewed by 172.69.59.155 for the first time.

 Viewed

March 13, 2026 @ 6:12 pm

Estimate viewed by 172.69.214.223 for the first time.

 Viewed

March 13, 2026 @ 6:12 pm

Estimate viewed by 172.70.50.43 for the first time.

 Viewed

March 13, 2026 @ 6:12 pm

Estimate viewed by 104.23.187.214 for the first time.

 Viewed

March 13, 2026 @ 6:12 pm

Estimate viewed by 172.69.17.138 for the first time.

 Viewed

March 14, 2026 @ 12:08 pm

Estimate viewed by 162.159.122.179 for the first time.

 Viewed

March 19, 2026 @ 8:45 pm

Estimate viewed by 172.71.166.223 for the first time.

 Viewed

March 19, 2026 @ 8:45 pm

Estimate viewed by 198.41.227.19 for the first time.

 Viewed

March 20, 2026 @ 5:24 pm

Estimate viewed by 172.69.7.16 for the first time.

 Viewed

March 20, 2026 @ 6:12 pm

Estimate viewed by 162.159.106.79 for the first time.

 Viewed

March 20, 2026 @ 6:12 pm

Estimate viewed by 172.71.195.92 for the first time.

 Viewed

March 20, 2026 @ 6:12 pm

Estimate viewed by 172.69.130.99 for the first time.

 Viewed

March 20, 2026 @ 6:12 pm

Estimate viewed by 172.71.155.172 for the first time.

 Viewed

March 20, 2026 @ 6:12 pm

Estimate viewed by 104.22.20.114 for the first time.

 Viewed

March 22, 2026 @ 10:32 pm

Estimate viewed by 104.22.64.80 for the first time.

 Viewed

March 22, 2026 @ 10:32 pm

Estimate viewed by 172.71.254.254 for the first time.

 Viewed

March 23, 2026 @ 4:35 pm

Estimate viewed by 104.22.62.106 for the first time.

 Viewed

March 26, 2026 @ 10:05 pm

Estimate viewed by 104.22.62.107 for the first time.

 Viewed

March 27, 2026 @ 12:00 pm

Estimate viewed by 108.162.216.153 for the first time.

 Viewed

March 31, 2026 @ 3:03 pm

Estimate viewed by 172.70.126.103 for the first time.

 Viewed

April 18, 2026 @ 8:21 am

Estimate viewed by 172.71.215.121 for the first time.

 Viewed

April 20, 2026 @ 1:55 pm

Estimate viewed by 172.68.229.221 for the first time.

 Viewed

April 25, 2026 @ 1:53 am

Estimate viewed by 172.69.9.39 for the first time.

 Viewed

April 25, 2026 @ 7:38 pm

Estimate viewed by 104.22.20.167 for the first time.

 Viewed

April 28, 2026 @ 12:17 am

Estimate viewed by 172.68.55.229 for the first time.



 Viewed

April 28, 2026 @ 10:59 pm

Estimate viewed by 162.158.126.214 for the first time.



 Viewed

April 29, 2026 @ 2:23 am

Estimate viewed by 172.68.81.148 for the first time.



 Viewed

May 14, 2026 @ 8:06 am

Estimate viewed by 104.22.17.145 for the first time.



 Viewed

May 14, 2026 @ 9:18 pm

Estimate viewed by 172.71.158.42 for the first time.



 Viewed

June 11, 2026 @ 3:52 am

Estimate viewed by 172.71.124.104 for the first time.



 Viewed

June 19, 2026 @ 12:54 am

Estimate viewed by 172.71.1.147 for the first time.



 Viewed

June 22, 2026 @ 8:27 pm

Estimate viewed by 162.158.186.127 for the first time.

