

```
body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals { page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; } #doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button, #doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border: none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding: 10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; } body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf } body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; } body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; } jQuery(document).ready(function() { jQuery("#invoice.sa_invoice-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("#estimate.sa_estimate-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href='#payment']").attr("href", "https://valleywidepro.com/estimate/be9b32911e1edd82db486851746315e/"); jQuery(".button.primary_button.purchase_button").attr("href", "https://valleywidepro.com/estimate/be9b32911e1edd82db486851746315e/"); jQuery(".button.primary_button.payment_option").attr("href", "https://valleywidepro.com/estimate/be9b32911e1edd82db486851746315e/"); jQuery("#change_payment_amount").attr("href", "https://valleywidepro.com/estimate/be9b32911e1edd82db486851746315e/"); });
```

(4922) Tile Roof Replace – 3470 S BARBERRY PL

[Print to PDF](#)[Accept Estimate](#)[Decline Estimate](#)

Arathena Sprankle
3470 S BARBERRY PL
CHANDLER, AZ 85248
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US



Date

February 4, 2025



Estimate Number

4922



Estimate Due

March 6, 2025



Estimate Total

\$1.00

Attachments



3470-South-Barberry-Place-Chandler-AZ-85248

Service

Price

% ?

Amount

ESTIMATE SPECS FOR TILE ROOF REPLACE *PLEASE SEE ROOFR SPECS ATTACHED*

\$1

0%

\$1

- —This proposal applies to the entire Tile Roof @ 21 sq's.
- —Remove tile then set aside, re-install after repair (unless broken—then replace).
- —Remove felt and remove and replace battens from the entire tile roof.
- —Remove and replace any sheets of bad plywood (as needed) throughout the roof. *Additional plywood billed at \$80/sheet.*
- —Install new SBS rolled roofing as needed.
- —Install new **[SEE BELOW]** underlayment over the entire tile roof.
- —Install new 3 inch x 3 inch drip edge around the perimeter of the entire tile roof.
- —Install new ribbed valley metals, and channel metals as needed throughout the tile roof.
- —Install new L metals, roof jacks, T-Top air vents, and O'Haggin vents throughout the tile roof as needed. (proper ventilation)
- —Install all new Fascia Board as needed.
- —Install new ridge and hip enclosures as needed throughout the tile roof.
- —Install new bird stops as needed throughout the tile roof.
- —Seal all penetrations, haul away debris and keep yard clean.
- —Provide **[SEE BELOW]** limited warranty against leaks over the entire Tile roof, @ 21 sq's.

ESTIMATED COMPLETION: 2-3 Days

WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed. Tax is included in price.

UNDERLAYMENT & WARRANTY OPTIONS BELOW:

- **GOOD (SINGLE-LAYER UNDERLAYMENT): \$8,390 – 10-YEAR LIMITED MANUFACTURER WARRANTY**
- **BETTER (DOUBLE-LAYER UNDERLAYMENT): \$8,980 – 20-YEAR LIMITED MANUFACTURER WARRANTY**
- **BEST (TILE SEAL UNDERLAYMENT): \$9,900 – 30-YEAR LIMITED MANUFACTURER WARRANTY**

**See warranty statement below.*

Subtotal \$0.00

Total \$1.00

Thank you; we really appreciate your business! Let us know if you have any questions about your estimate.

Please see attachments for full roof report information.

50% is due prior to the beginning of the project. 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, LLC, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Phone: (877) 692-9762
Email: info@azroc.gov
Address: Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812
Website: www.azroc.gov

Please reference our license number [ROC# 348219](#) when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

Warranty Statement for Roof Replacement Options

Thank you for choosing Valleywide Pro Roofing, LLC for your roofing needs. We are committed to providing high-quality materials and professional installation to ensure the longevity and performance of your new roof. To maximize the lifespan of your roof and maintain warranty coverage, the following warranty terms and conditions apply:

1. Warranty Coverage

All roof replacement options come with a comprehensive warranty that includes:

Underlayment Warranty: Coverage as per the manufacturer's warranty, ranging from 10 to 50 years depending on the underlayment type selected.

Tile Warranty: Coverage as per the manufacturer's warranty, ranging from 30 years to a lifetime, depending on the type of tile selected (standard concrete, premium concrete, or clay tiles).

2. Maintenance Requirements

To maintain the validity of the warranty beyond the initial 15 years, an **annual maintenance package** is required. This package is designed to ensure your roof remains in optimal condition and any potential issues are addressed promptly.

Annual Maintenance Package Cost: \$299/year.

Discounted Maintenance Plan: Customers have the option to pre-pay for maintenance in 5-year bundles at a discounted rate. See below for discounts.

Discounted Rates:

5-Year Maintenance Bundle: \$1,345 (a savings of \$150 compared to annual payments).

3. Manufacturer Warranty Claims

While Valleywide Pro Roofing, LLC provides a workmanship warranty on the installation and materials used, any claims related to the manufacturer's warranties (underlayment and tiles) must be processed directly through the manufacturer. Our team is available to assist you in facilitating these claims to ensure a smooth and efficient process.

4. Terms and Conditions

Warranty Activation: The warranty will become effective on the date of completion of the roof installation.

Maintenance Schedule: The annual maintenance package is mandatory after the initial 5-year period to continue the coverage. Failure to comply with the annual maintenance schedule may void the warranty.








Coverage Exclusions: The warranty does not cover damage caused by natural disasters, improper use, or modifications made to the roof after installation without prior consultation with Valleywide Pro Roofing, LLC. The warranty does not cover any work performed by other roofing contractors or companies not associated with Valleywide Pro Roofing, LLC.


Warranty Transfer: The warranty is transferable to a new homeowner upon the sale of the property, provided that all maintenance requirements have been met. A **one-time transfer fee of \$250** is required to transfer the warranty to the new homeowner.

We appreciate your business and are dedicated to providing you with a roof that offers protection and peace of mind for years to come. If you have any questions regarding the warranty or maintenance packages, please do not hesitate to contact us.

<https://valleywidepro.com> billing@valleywidepro.com



-  **Updated**
February 4, 2025 @ 5:06 pm Estimate updated by valleywide.
-  **Updated**
February 4, 2025 @ 5:07 pm Estimate updated by valleywide.
-  **Updated**
February 4, 2025 @ 5:07 pm Estimate updated by valleywide.
-  **Viewed**
February 4, 2025 @ 5:08 pm Estimate viewed by (valleywide) for the first time.
-  **Viewed**
February 4, 2025 @ 5:08 pm Estimate viewed by for the first time.
-  **Viewed**
February 4, 2025 @ 5:08 pm Estimate viewed by 172.69.34.141 for the first time.
-  **Viewed**
February 4, 2025 @ 5:09 pm Estimate viewed by 172.70.214.154 for the first time.

-  **Viewed**
February 4, 2025 @ 5:09 pm
Estimate viewed by 162.158.187.70 for the first time.
-  **Updated**
February 4, 2025 @ 5:11 pm
Estimate updated by valleywide.
-  **Viewed**
February 4, 2025 @ 5:12 pm
Estimate viewed by 172.69.17.206 for the first time.
-  **Viewed**
February 6, 2025 @ 5:11 pm
Estimate viewed by 172.71.166.165 for the first time.
-  **Viewed**
February 6, 2025 @ 5:11 pm
Estimate viewed by 172.71.195.69 for the first time.
-  **Viewed**
February 6, 2025 @ 5:16 pm
Estimate viewed by 172.70.206.72 for the first time.
-  **Viewed**
February 7, 2025 @ 9:13 pm
Estimate viewed by 172.70.94.133 for the first time.
-  **Viewed**
February 11, 2025 @ 12:12 am
Estimate viewed by 172.70.126.37 for the first time.
-  **Viewed**
February 12, 2025 @ 10:22 pm
Estimate viewed by 172.70.214.24 for the first time.
-  **Viewed**
February 14, 2025 @ 2:37 am
Estimate viewed by 172.69.17.80 for the first time.
-  **Viewed**
February 21, 2025 @ 9:47 am
Estimate viewed by 172.70.210.104 for the first time.
-  **Viewed**
February 23, 2025 @ 12:53 pm
Estimate viewed by 172.69.17.202 for the first time.
-  **Viewed**
March 4, 2025 @ 2:36 am
Estimate viewed by 104.23.166.154 for the first time.

 **Viewed**
March 13, 2025 @ 11:09 pm

Estimate viewed by 172.69.17.18 for the first time.

 **Viewed**
March 18, 2025 @ 6:21 pm

Estimate viewed by 198.41.227.81 for the first time.

 **Viewed**
March 19, 2025 @ 2:22 pm

Estimate viewed by 172.68.35.88 for the first time.

 **Viewed**
April 4, 2025 @ 5:39 pm

Estimate viewed by 172.70.126.165 for the first time.

 **Viewed**
April 4, 2025 @ 6:48 pm

Estimate viewed by 172.70.127.118 for the first time.

 **Viewed**
June 5, 2025 @ 3:04 am

Estimate viewed by 172.69.58.239 for the first time.

 **Viewed**
June 11, 2025 @ 2:03 am

Estimate viewed by 172.71.254.148 for the first time.

 **Viewed**
June 12, 2025 @ 2:50 pm

Estimate viewed by 172.69.17.19 for the first time.

 **Viewed**
June 29, 2025 @ 7:23 pm

Estimate viewed by 172.70.210.86 for the first time.

 **Viewed**
June 30, 2025 @ 9:08 pm

Estimate viewed by 172.71.254.132 for the first time.

 **Viewed**
July 5, 2025 @ 6:57 pm

Estimate viewed by 172.70.208.77 for the first time.

 **Viewed**
August 17, 2025 @ 8:42 am

Estimate viewed by 172.71.154.153 for the first time.

 Viewed
September 12, 2025 @ 2:51 am

Estimate viewed by 172.70.126.106 for the first time.

 Viewed
September 16, 2025 @ 7:25 am

Estimate viewed by 104.23.209.93 for the first time.

 Viewed
September 16, 2025 @ 11:57 am

Estimate viewed by 104.23.213.160 for the first time.

 Viewed
September 18, 2025 @ 9:41 pm

Estimate viewed by 172.71.254.131 for the first time.

 Viewed
October 30, 2025 @ 1:59 am

Estimate viewed by 172.69.59.44 for the first time.

 Viewed
November 22, 2025 @ 5:09 am

Estimate viewed by 172.70.135.15 for the first time.

 Viewed
December 4, 2025 @ 9:12 am

Estimate viewed by 162.158.190.94 for the first time.

 Viewed
December 16, 2025 @ 11:57 pm

Estimate viewed by 172.70.100.99 for the first time.

 Viewed
December 17, 2025 @ 9:20 am

Estimate viewed by 172.69.59.33 for the first time.

 Viewed
December 17, 2025 @ 8:22 pm

Estimate viewed by 172.69.214.242 for the first time.

 Viewed
January 6, 2026 @ 6:40 am

Estimate viewed by 172.70.42.238 for the first time.

 Viewed
January 17, 2026 @ 7:36 pm

Estimate viewed by 162.158.162.107 for the first time.

 Viewed
January 19, 2026 @ 10:49 am

Estimate viewed by 162.158.91.129 for the first time.

 Viewed

February 3, 2026 @ 9:09 pm

Estimate viewed by 104.23.213.80 for the first time.

 Viewed

February 6, 2026 @ 3:12 am

Estimate viewed by 104.23.239.144 for the first time.

 Viewed

February 27, 2026 @ 10:33 pm

Estimate viewed by 104.23.170.98 for the first time.

 Viewed

March 14, 2026 @ 9:00 pm

Estimate viewed by 172.69.7.16 for the first time.

 Viewed

March 14, 2026 @ 10:34 pm

Estimate viewed by 104.22.62.106 for the first time.

 Viewed

March 16, 2026 @ 3:12 am

Estimate viewed by 172.70.126.103 for the first time.

 Viewed

March 16, 2026 @ 5:58 am

Estimate viewed by 172.70.94.48 for the first time.

 Viewed

April 29, 2026 @ 8:44 am

Estimate viewed by 172.64.223.134 for the first time.

 Viewed

May 23, 2026 @ 11:19 am

Estimate viewed by 172.70.100.159 for the first time.

