

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:"ctlSignature",SignWidth:
'450",TransparentSign:"true",SignHeight:"300",leModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor:
"#FFFFFF", BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-
pro/bundles/sprout-invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-
invoices-pro/bundles/sprout-invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.",
ErrorMessage: "Please continue with a valid signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.",
SignzIndex: 1000, Visible: "true", forceMouseEvent: true, Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init();
$("#sign_doc").on('click', function(event) { event.preventDefault(); // scroll to signature $(html, body).animate({ scrollTop:
$("#ctlSignature_Container").offset().top }, 1000); }); $("#save_signature_via_ajax").on('click', function(event) { if (! ValidateSignature() ) { return; }
var sig_data = $("#ctlSignature_data").val(), sig_data_smooth = $("#ctlSignature_data_canvas").val(); $(this).after(si_js_object.inline_spinner);
$.post( si_js_object.ajax_url, { action: 'si_save_signature', invoice_id: 3833, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce:
si_js_object.security }, function( response ) { $('spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $('#sign_doc').hide();
$("#ctlSignature_toolbar").hide(); // show signature $('#si_signature_wrap').html( response.data.img ); // Add ability to pay $(
'stipe_checkout_button').show(); $('.square_checkout').show(); $('.button.status_change').show(); $('a.button.primary_button.purchase_button'
).show(); $('a.button.primary_button.payment_option').show(); // New Theme $('#paybar_inner.button.open').show(); // scroll to the top $(html,
body).animate({ scrollTop: $("#outer_doc_wrap").offset().top }, 500); } else { $("#save_signature_via_ajax").after(" + response.data.message + "); }
}); //> body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals {
page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; }
#doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button,
#doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border:
none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding:
10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; }
body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf }
body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-
color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; }
body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; }
jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf');
jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href",
"https://valleywidepro.com/estimate/bea94d82df95c830363aaf543a3cffbc/"); jQuery(".button.primary_button.purchase_button").attr("href",
"https://valleywidepro.com/estimate/bea94d82df95c830363aaf543a3cffbc/"); jQuery(".button.primary_button.payment_option").attr("href",
"https://valleywidepro.com/estimate/bea94d82df95c830363aaf543a3cffbc/"); jQuery("#change_payment_amount").attr("href",
"https://valleywidepro.com/estimate/bea94d82df95c830363aaf543a3cffbc/"); });
```

(3833) Foam Installation & Stucco Repair – 12561 N Red Eagle Dr

.button.status_change, a.button.primary_button.purchase_button, a.button.primary_button.payment_option { display: none; } .stipe_checkout_button { display: none; } .square_checkout { display: none; } .button.status_change[data-status-change=decline] { display: inline-block !important; }

[Decline Estimate](#)

[Signature Required](#)

[Print to PDF](#)

[Accept Estimate](#)

Nathaniel Nelson
12561 N Red Eagle Dr
Oro Valley, AZ 85755
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US



Date

November 1, 2024



Estimate Number

3833



Estimate Due

December 1, 2024

Estimate Total

\$23,000.00

Service	Price	Amount
<p>—This estimate applies to the entire roof @ 53 sq's.</p> <p>—Remove current layers of roofing system & membrane. —Remove and replace any bad plywood as needed throughout the roof. <i>Additional plywood sheets (if needed) would add approx. \$30 per sheet to the total (cost of plywood plus cost of install/discard of old sheets).</i></p> <p>—Apply new foam over the entire roof. Low spots will be filled in with additional foam as/where needed. —Install 3 inch x 3 inch drip edge around the perimeter of the entire roof as needed. —Install new 2x4 Skylight. —Patch current stucco and apply foam over cracked stucco. Match color as much as possible (tan color). —Paint Tan color over edges to match color of property. —Install new L/roof jack flashings throughout the roof as needed. —Seal all penetrations, haul away debris and keep yard clean. —Provide 5-year warranty against leaks over the entire roof, @ 53 sq's.</p> <p>ESTIMATED COMPLETION: 1-2 Days</p> <p>WE PROPOSE hereby to furnish material and labor – complete in accordance with the above specifications, for the sum listed below. Tax is included in price.</p>	\$23,000	\$23,000

	Subtotal	\$0.00
	Total	\$23,000.00

Thank you; we really appreciate your business! Let us know if you have any questions about your estimate.

To approve this estimate, 50% is due prior to the beginning of the project. 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Phone: (877) 692-9762

Email: info@azroc.gov

Address: Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812

Website: www.azroc.gov

Please reference our license number ROC# 348219 when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

To approve this estimate, 50% is due prior to the beginning of the project.

Save Signature!

<https://valleywidepro.com> billing@valleywidepro.com



 Updated

November 4, 2024 @ 12:19 am

Estimate updated by valleywide.

 Updated

November 4, 2024 @ 12:21 am

Estimate updated by valleywide.

 Updated

November 4, 2024 @ 12:22 am

Estimate updated by valleywide.

 Viewed

November 4, 2024 @ 1:17 pm

Estimate viewed by (valleywide) for the first time.

 Viewed

November 4, 2024 @ 1:17 pm

Estimate viewed by 172.70.206.234 for the first time.

 Viewed

November 4, 2024 @ 1:19 pm

Estimate viewed by 162.158.41.102 for the first time.

 Viewed

November 4, 2024 @ 1:19 pm

Estimate viewed by 162.158.41.71 for the first time.

 Viewed

November 4, 2024 @ 1:19 pm

Estimate viewed by 172.71.167.73 for the first time.

 Viewed

November 4, 2024 @ 1:30 pm

Estimate viewed by for the first time.

 Viewed

November 4, 2024 @ 1:30 pm

Estimate viewed by 172.71.254.125 for the first time.

 Viewed

November 4, 2024 @ 1:50 pm

Estimate viewed by 172.70.206.235 for the first time.

 Viewed

November 4, 2024 @ 1:53 pm

Estimate viewed by 172.69.59.108 for the first time.

Estimate viewed by 172.69.58.228 for the first time.

 Viewed

November 4, 2024 @ 1:53 pm

Estimate viewed by 172.70.131.116 for the first time.

 Viewed

November 4, 2024 @ 1:53 pm

 Viewed

November 4, 2024 @ 2:01 pm

Estimate viewed by 172.69.33.175 for the first time.

 Updated

November 4, 2024 @ 2:09 pm

Estimate updated by valleywide.

 Viewed

November 4, 2024 @ 2:10 pm

Estimate viewed by 172.70.214.232 for the first time.

 Updated

November 4, 2024 @ 2:17 pm

Estimate updated by valleywide.

 Updated

November 4, 2024 @ 2:19 pm

Estimate updated by valleywide.

 Viewed

November 4, 2024 @ 2:19 pm

Estimate viewed by 172.69.33.244 for the first time.

 Updated

November 4, 2024 @ 2:23 pm

Estimate updated by valleywide.

 Updated

November 4, 2024 @ 2:24 pm

Estimate updated by valleywide.

 Updated

November 4, 2024 @ 2:28 pm

Estimate updated by valleywide.

 Viewed

November 4, 2024 @ 2:28 pm

Estimate viewed by 172.69.59.9 for the first time.

 Viewed

November 4, 2024 @ 3:43 pm


Estimate viewed by 172.70.211.109 for the first time.

 Viewed
November 4, 2024 @ 3:56 pm

Estimate viewed by 172.70.206.81 for the first time.

 Viewed
November 4, 2024 @ 3:58 pm

Estimate viewed by 172.70.211.202 for the first time.

 Viewed
November 13, 2024 @ 8:18 am

Estimate viewed by 162.158.90.75 for the first time.

 Viewed
January 26, 2025 @ 10:15 am

Estimate viewed by 172.69.34.207 for the first time.

 Viewed
January 26, 2025 @ 10:15 am

Estimate viewed by 198.41.227.9 for the first time.

 Viewed
January 26, 2025 @ 10:15 am

Estimate viewed by 172.71.254.47 for the first time.

 Viewed
February 11, 2025 @ 12:14 am

Estimate viewed by 172.70.131.131 for the first time.

 Viewed
February 14, 2025 @ 2:43 am

Estimate viewed by 172.69.17.18 for the first time.

 Viewed
February 23, 2025 @ 1:32 pm

Estimate viewed by 172.71.254.158 for the first time.

 Viewed
March 1, 2025 @ 5:48 pm

Estimate viewed by 172.68.164.96 for the first time.

 Viewed
April 13, 2025 @ 10:00 pm

Estimate viewed by 172.70.49.145 for the first time.

 Viewed
May 9, 2025 @ 1:28 am

Estimate viewed by 172.70.126.112 for the first time.

 Viewed

June 3, 2025 @ 11:07 am

Estimate viewed by 172.69.65.42 for the first time.

 Viewed

June 3, 2025 @ 1:30 pm

Estimate viewed by 172.68.150.8 for the first time.

 Viewed

June 5, 2025 @ 3:14 am

Estimate viewed by 172.70.131.168 for the first time.

 Viewed

June 10, 2025 @ 6:40 pm

Estimate viewed by 172.70.194.176 for the first time.

 Viewed

June 11, 2025 @ 7:59 am

Estimate viewed by 172.69.59.134 for the first time.

 Viewed

June 30, 2025 @ 2:08 am

Estimate viewed by 162.158.187.115 for the first time.

 Viewed

July 1, 2025 @ 9:26 am

Estimate viewed by 172.68.151.116 for the first time.

 Viewed

July 31, 2025 @ 5:37 am

Estimate viewed by 104.23.190.36 for the first time.

 Viewed

September 5, 2025 @ 5:48 am

Estimate viewed by 172.69.7.153 for the first time.

 Viewed

September 6, 2025 @ 2:13 am

Estimate viewed by 172.68.164.12 for the first time.

 Viewed

September 9, 2025 @ 10:35 am

Estimate viewed by 172.71.203.128 for the first time.

 Viewed

September 10, 2025 @ 10:35 am

Estimate viewed by 141.101.99.9 for the first time.

-  **Viewed**
September 12, 2025 @ 2:50 am
Estimate viewed by 172.71.255.2 for the first time.
-  **Viewed**
September 18, 2025 @ 9:45 pm
Estimate viewed by 172.69.59.147 for the first time.
-  **Viewed**
October 30, 2025 @ 2:26 am
Estimate viewed by 172.69.7.44 for the first time.
-  **Viewed**
November 6, 2025 @ 3:55 am
Estimate viewed by 172.69.59.148 for the first time.
-  **Viewed**
November 22, 2025 @ 10:53 am
Estimate viewed by 172.70.135.16 for the first time.
-  **Viewed**
December 6, 2025 @ 9:09 am
Estimate viewed by 162.158.108.99 for the first time.
-  **Viewed**
December 23, 2025 @ 5:20 pm
Estimate viewed by 162.158.78.206 for the first time.
-  **Viewed**
December 31, 2025 @ 1:25 am
Estimate viewed by 172.70.43.33 for the first time.
-  **Viewed**
January 8, 2026 @ 11:28 am
Estimate viewed by 172.69.59.156 for the first time.
-  **Viewed**
January 23, 2026 @ 8:21 am
Estimate viewed by 162.158.186.34 for the first time.
-  **Viewed**
February 3, 2026 @ 1:32 pm
Estimate viewed by 104.23.213.80 for the first time.
-  **Viewed**
February 6, 2026 @ 3:13 am
Estimate viewed by 104.23.239.144 for the first time.

 Viewed

March 2, 2026 @ 7:44 pm

Estimate viewed by 108.162.216.153 for the first time.

 Viewed

March 17, 2026 @ 1:49 am

Estimate viewed by 172.70.215.59 for the first time.

 Viewed

March 19, 2026 @ 11:34 pm

Estimate viewed by 172.69.65.199 for the first time.

 Viewed

March 19, 2026 @ 11:34 pm

Estimate viewed by 172.70.94.138 for the first time.

 Viewed

March 21, 2026 @ 9:52 am

Estimate viewed by 172.71.254.254 for the first time.

 Viewed

March 22, 2026 @ 9:58 am

Estimate viewed by 104.22.62.106 for the first time.

 Viewed

March 23, 2026 @ 8:03 pm

Estimate viewed by 104.22.64.81 for the first time.

 Viewed

March 24, 2026 @ 10:49 pm

Estimate viewed by 172.69.17.138 for the first time.

 Viewed

March 25, 2026 @ 10:57 am

Estimate viewed by 172.69.7.15 for the first time.

 Viewed

March 27, 2026 @ 12:06 am

Estimate viewed by 172.70.94.49 for the first time.

 Viewed

March 27, 2026 @ 12:06 am

Estimate viewed by 198.41.227.18 for the first time.

 Viewed

March 27, 2026 @ 8:23 pm

Estimate viewed by 108.162.216.152 for the first time.

 Viewed

March 28, 2026 @ 9:44 am

Estimate viewed by 172.69.17.139 for the first time.

