

```
body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals { page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; } #doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button, #doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border: none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding: 10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; } body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf } body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; } body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; } jQuery(document).ready(function() { jQuery("#invoice.sa_invoice-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("#estimate.sa_estimate-template-default").find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href", "https://valleywidepro.com/estimate/f1431f800529242b46b806083665a99f/"); jQuery(".button.primary_button.purchase_button").attr("href", "https://valleywidepro.com/estimate/f1431f800529242b46b806083665a99f/"); jQuery(".button.primary_button.payment_option").attr("href", "https://valleywidepro.com/estimate/f1431f800529242b46b806083665a99f/"); jQuery("#change_payment_amount").attr("href", "https://valleywidepro.com/estimate/f1431f800529242b46b806083665a99f/"); });
```

7593

Print to PDF

Accept Estimate

Declined

Emily Anderson
5623 W STARGAZER PL
LAVEEN, AZ 85339
US



Valleywide Pro Roofing 4022 W
Palo Verde Dr
Phoenix, AZ 85019
US

Date

July 31, 2025

Estimate Number

7593

Estimate Due

August 30, 2025

Estimate Total

\$550.00

Service

Price

Amount

- Remove & replace 3 broken tiles (match tile color as close

\$550

\$550

as possible).

- All mortar joints will be touched up as needed.
- Secure slipped tiles as needed.
- Seal all penetrations. Paint all penetrations to match roof color.
- Seal gap and secure sheeting on backside of house.
- Clean up debris and leave yard clean.

Please Note: SIX MONTH WORKMANSHIP WARRANTY provided.

Subtotal	\$0.00
-----------------	--------

Total	\$550.00
--------------	----------

Thank you; we really appreciate your business! Let us know if you have any questions about your estimate.

To approve this estimate, 50% is due prior to the beginning of the project. 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

Phone: (877) 692-9762

Email: info@azroc.gov

Address: Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812

Website: www.azroc.gov

Please reference our license number ROC# 348219 when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

To approve this estimate, 50% is due prior to the beginning of the project.

<https://valleywidepro.com> billing@valleywidepro.com



 Viewed

August 2, 2025 @ 12:45 pm

Estimate viewed by for the first time.

 Viewed

August 3, 2025 @ 4:21 am

Estimate viewed by 172.69.7.71 for the first time.

 Viewed

August 5, 2025 @ 10:28 am

Estimate viewed by 108.162.216.144 for the first time.

 Viewed

August 10, 2025 @ 4:07 am

Estimate viewed by 172.68.70.214 for the first time.

 Viewed

August 30, 2025 @ 7:30 am

Estimate viewed by 104.23.195.46 for the first time.

 Status Update

August 30, 2025 @ 7:31 am

Status changed: Pending to **Declined**.

 Viewed

August 30, 2025 @ 11:38 am

Estimate viewed by 172.69.74.234 for the first time.

 Viewed

August 31, 2025 @ 3:43 pm

Estimate viewed by 172.69.17.203 for the first time.

 Viewed

September 9, 2025 @ 5:41 pm

Estimate viewed by 172.69.74.253 for the first time.

 Viewed

September 17, 2025 @ 12:29 am

Estimate viewed by 172.70.140.205 for the first time.

 Viewed

September 20, 2025 @ 11:41 am

Estimate viewed by 172.70.179.45 for the first time.

 Viewed

September 21, 2025 @ 12:13 pm

Estimate viewed by 104.23.221.219 for the first time.

Estimate viewed by 172.71.8.31 for the first time.

 Viewed

September 22, 2025 @ 7:03 pm

Estimate viewed by 162.158.128.146 for the first time.

 Viewed

September 24, 2025 @ 8:32 am

 Viewed

September 25, 2025 @ 9:27 pm

Estimate viewed by 172.71.238.125 for the first time.

 Viewed

September 27, 2025 @ 5:38 pm

Estimate viewed by 172.71.234.129 for the first time.

 Viewed

September 29, 2025 @ 8:02 pm

Estimate viewed by 172.71.238.124 for the first time.

 Viewed

October 5, 2025 @ 1:20 am

Estimate viewed by 172.69.201.147 for the first time.

 Viewed

October 5, 2025 @ 1:22 am

Estimate viewed by 172.71.254.130 for the first time.

 Viewed

October 5, 2025 @ 1:22 am

Estimate viewed by 172.70.83.32 for the first time.

 Viewed

October 7, 2025 @ 2:31 am

Estimate viewed by 172.70.108.170 for the first time.

 Viewed

October 9, 2025 @ 7:30 pm

Estimate viewed by 172.71.214.175 for the first time.

 Viewed

October 12, 2025 @ 11:37 am

Estimate viewed by 104.23.248.183 for the first time.

 Viewed

October 13, 2025 @ 5:59 pm

Estimate viewed by 172.71.192.152 for the first time.

 Viewed

October 15, 2025 @ 1:49 pm

Estimate viewed by 172.69.138.96 for the first time.

 Viewed

October 17, 2025 @ 1:01 pm

Estimate viewed by 162.158.88.76 for the first time.

 Viewed

October 21, 2025 @ 2:15 am

Estimate viewed by 172.69.138.111 for the first time.

 Viewed

October 22, 2025 @ 6:13 pm

Estimate viewed by 172.70.140.204 for the first time.

 Viewed

October 24, 2025 @ 2:06 am

Estimate viewed by 104.23.251.91 for the first time.

 Viewed

October 25, 2025 @ 11:30 am

Estimate viewed by 172.71.152.29 for the first time.

 Viewed

October 27, 2025 @ 10:57 am

Estimate viewed by 172.69.39.24 for the first time.

 Viewed

October 30, 2025 @ 5:02 am

Estimate viewed by 162.158.163.126 for the first time.

 Viewed

October 30, 2025 @ 6:02 am

Estimate viewed by 172.68.164.13 for the first time.

 Viewed

October 31, 2025 @ 8:29 am

Estimate viewed by 162.158.88.77 for the first time.

 Viewed

April 6, 2026 @ 10:51 pm

Estimate viewed by 162.158.167.169 for the first time.

 Viewed

April 25, 2026 @ 3:35 pm

Estimate viewed by 172.68.211.220 for the first time.

 Viewed

April 27, 2026 @ 5:48 pm

Estimate viewed by 162.159.98.165 for the first time.

 Viewed

May 2, 2026 @ 8:58 am

Estimate viewed by 172.70.179.88 for the first time.



 Viewed

May 4, 2026 @ 2:01 am

Estimate viewed by 172.69.7.16 for the first time.

