

```
var signObjects = new Array('ctlSignature'); var objctlSignature = new SuperSignature({SignObject:"ctlSignature",SignWidth:
'450",TransparentSign:"true",SignHeight:"300",IsModalFix: false,PenColor: "#0000FF",BorderStyle: "Dashed",BorderWidth: "2px",BackColor:
"#FFFFFF", BorderColor: "#DDDDDD",RequiredPoints: "15",ClearImage:"https://valleywidepro.com/wp-content/plugins/sprout-invoices-
pro/bundles/sprout-invoices-addon-esignature/resources/ss/erase.png", PenCursor:"https://valleywidepro.com/wp-content/plugins/sprout-
invoices-pro/bundles/sprout-invoices-addon-esignature/resources/ss/pen.cur", StartMessage: "Please provide your signature above.",
ErrorMessage: "Please continue with a valid signature above.",SuccessMessage: "Thank you! Please save your signature before proceeding.",
SignzIndex: 1000, Visible: "true", forceMouseEvent: true, Enabled: "true"}); //<![CDATA[ jQuery(document).ready( function($) { objctlSignature.Init();
$("#sign_doc").on('click', function(event) { event.preventDefault(); // scroll to signature $('html, body').animate({ scrollTop:
$("#ctlSignature_Container").offset().top }, 1000); }); $("#save_signature_via_ajax").on('click', function(event) { if ( ! ValidateSignature() ) { return; }
var sig_data = $("#ctlSignature_data").val(), sig_data_smooth = $("#ctlSignature_data_canvas").val(); $(this).after(si_js_object.inline_spinner);
$.post( si_js_object.ajax_url, { action: 'si_save_signature', invoice_id: 5725, sig_data: sig_data, sig_canvas_data: sig_data_smooth, nonce:
si_js_object.security }, function( response ) { $('spinner').hide(); if ( response.success ) { // hide sig options $(this).hide(); $("#sign_doc").hide();
$("#ctlSignature_toolbar").hide(); // show signature $("#si_signature_wrap").html( response.data.img ); // Add ability to pay $(
'stipe_checkout_button').show(); $('.square_checkout').show(); $('.button.status_change').show(); $('a.button.primary_button.purchase_button'
).show(); $('a.button.primary_button.payment_option').show(); // New Theme $("#paybar_inner.button.open").show(); // scroll to the top $('html,
body').animate({ scrollTop: $("#outer_doc_wrap").offset().top }, 500); } else { $("#save_signature_via_ajax").after(" + response.data.message + "); }
}); //> body { background-color: transparent; } img, p, li, .line_item, .si_default_theme .item, #line_items_footer, #footer_wrap, #totals {
page-break-inside:avoid } #paybar { position: static !important; } #outer_doc_wrap { margin: 0 10px 10px 10px; }
#doc_header_wrap.sticky_header, .stuck #doc_header_wrap.sticky_header { position: static !important; border: none; } #print_to_pdf_button,
#doc_history, .purchase_button:after, .si_default_theme .row.history_message, .li_comments_toggle { display: none; } #document_wrap { border:
none; } .newcf { overflow: auto; } body.si_default_theme #header .messages { min-height: 10px; } body.si_default_theme #header .inner { padding:
10px 0px !important; } body.si_default_theme, body#estimate.sa_estimate-template-default { background-color: #fff; color: #333; }
body.si_default_theme .title, body.si_default_theme #intro .inner .column span, body.si_default_theme #notes .item .header h3 { color: #afafaf }
body.si_default_theme .title:after, body.si_default_theme #items .items .item .column h3, body.si_default_theme #notes .item .header h3 { border-
color: #eee; } body.si_default_theme .title h2 { background-color: #eee; } body.si_default_theme header#header { background-color: #f7f7f7; }
body.si_default_theme section#paybar { background-color: #f7f7f7; } .si_basic_theme .history_message, #payment .inner { display: none; }
jQuery(document).ready(function() { jQuery('#invoice.sa_invoice-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf');
jQuery('#estimate.sa_estimate-template-default').find('.clearfix').removeClass('clearfix').addClass('newcf'); jQuery("a[href=#payment]").attr("href",
"https://valleywidepro.com/estimate/fd3137220576fe088c8ae51f1b9d8e87/"); jQuery(".button.primary_button.purchase_button").attr("href",
"https://valleywidepro.com/estimate/fd3137220576fe088c8ae51f1b9d8e87/"); jQuery(".button.primary_button.payment_option").attr("href",
"https://valleywidepro.com/estimate/fd3137220576fe088c8ae51f1b9d8e87/"); jQuery("#change_payment_amount").attr("href",
"https://valleywidepro.com/estimate/fd3137220576fe088c8ae51f1b9d8e87/"); });
```

## (5725) Full Shingle Replace – 4518 CHICAGO ST

.button.status\_change, a.button.primary\_button.purchase\_button, a.button.primary\_button.payment\_option { display: none; } .stipe\_checkout\_button { display: none; } .square\_checkout { display: none; } .button.status\_change[data-status-change=decline] { display: inline-block !important; }

[Decline Estimate](#)

[Signature Required](#)

[Print to PDF](#)

[Accept Estimate](#)

**Nicholle Grant & Eric Thomas**  
4518 W Chicago St  
Chandler, AZ 85226  
US



**Valleywide Pro Roofing** 4022 W  
Palo Verde Dr  
Phoenix, AZ 85019  
US



Date

April 14, 2025



Estimate Number

5725



Estimate Due

May 14, 2025



Estimate Total

\$13,900.00

Service	Price	Amount
<ul style="list-style-type: none"> <li>• This applies to the entire shingle roof, @ <b>34 sq's</b>.</li> <li>• Remove shingles and felt from the entire roof.</li> <li>• Remove and replace (20) sheets of bad plywood at \$85/sheet as needed throughout the shingle roof.</li> <li>• Install new <b>Underlayment</b> over the entire shingle roof.</li> <li>• Install new 30-year <b>shingles</b> over the entire shingle roof.</li> <li>• Install 35 new black 2"x2" drip edge and trim around the perimeter of the entire shingle roof as needed.</li> <li>• Install 110 lft of ridge of the shingle roof.</li> <li>• Install L flashings as needed on the shingle roof.</li> <li>• Install new Fascia along the perimeter of the shingle roof (as needed).</li> <li>• Remove and replace O'Haggin air vents on the shingle roof as needed.</li> <li>• Seal all penetrations, haul away debris, and keep yard clean.</li> <li>• <b>Provide 15-year Warranty*</b> against leaks over the entire shingle roof, @ 34 sq's.</li> </ul> <p><i>*See warranty statement below.</i></p>	\$13,900	\$13,900

	<b>Subtotal</b>	\$0.00
	<b>Total</b>	\$13,900.00

Thank you; we really appreciate your business! Please be sure to leave us a review upon completion of your project – we reward any reviews with a special gift! Referrals are our lifeline, please tell your neighbors about Valleywide Pro Roofing!

To approve this estimate, 50% is due prior to the beginning of the project. 50% due upon completion.

Customer Satisfaction Statement

At Valleywide Pro Roofing, we are dedicated to delivering the highest quality roofing services. We adhere strictly to the professional standards and are committed to ensuring your complete satisfaction. If you believe that your rights as a customer

have been violated, we encourage you to submit a complaint to the Arizona Registrar of Contractors (AZROC) within 30 days of the incident.

For your convenience, here's the contact information for the AZROC:

**Phone:** (877) 692-9762  
**Email:** [info@azroc.gov](mailto:info@azroc.gov)  
**Address:** Arizona Registrar of Contractors, 1700 W. Washington St. Suite 105, Phoenix, AZ 85007-2812  
**Website:** [www.azroc.gov](http://www.azroc.gov)

Please reference our license number [ROC#348219](#) when submitting your complaint. We value your trust and business, and we stand ready to address any concerns you may have.

---

## Warranty Statement for Roof Replacement Options

Thank you for choosing Valleywide Pro Roofing, LLC for your roofing needs. We are committed to providing high-quality materials and professional installation to ensure the longevity and performance of your new roof. To maximize the lifespan of your roof and maintain warranty coverage, the following warranty terms and conditions apply:

### 1. Warranty Coverage

All roof replacement options come with a comprehensive warranty that includes:

**Underlayment Warranty:** Coverage as per the manufacturer's warranty, ranging from 10 to 50 years depending on the underlayment type selected.

**Tile Warranty:** Coverage as per the manufacturer's warranty, ranging from 30 years to a lifetime, depending on the type of tile selected (standard concrete, premium concrete, or clay tiles).

**Shingle Warranty:** Coverage as per the manufacturer's warranty, typically ranging from 20 to 50 years depending on the type and grade of shingles selected (standard 3-tab, architectural, or premium shingles).

### 2. Maintenance Requirements

To maintain the validity of the warranty beyond the initial 10 years, an **annual maintenance package** is required. This package is designed to ensure your roof remains in optimal condition and any potential issues are addressed promptly.

**Annual Maintenance Package Cost:** \$299/year.

**Discounted Maintenance Plan:** Customers have the option to pre-pay for maintenance in 5-year bundles at a discounted rate. See below for this rate!

Discounted Rates:

**5-Year Maintenance Bundle:** \$1,345 (a savings of \$150 compared to annual payments).

### 3. Manufacturer Warranty Claims

While Valleywide Pro Roofing, LLC provides a workmanship warranty on the installation and materials used, any claims related to the manufacturer's warranties (underlayment, tiles, and shingles) must be processed directly through the manufacturer. Our team is available to assist you in facilitating these claims to ensure a smooth and efficient process.

### 4. Terms and Conditions

**Warranty Activation:** The warranty will become effective on the date of completion of the roof installation.

**Maintenance Schedule:** The annual maintenance package is mandatory after the initial 5-year period to continue the coverage. Failure to comply with the annual maintenance schedule may void the warranty.

**Coverage Exclusions:** The warranty does not cover damage caused by natural disasters, improper use, or modifications made to the roof after installation without prior consultation with Valleywide Pro Roofing, LLC. The warranty does not cover any work performed by other roofing contractors or companies not associated with Valleywide Pro Roofing, LLC.

**Warranty Transfer:** The warranty is transferable to a new homeowner upon the sale of the property, provided that all maintenance requirements have been met. A **one-time transfer fee of \$250** is required to transfer the warranty to the new homeowner.

We appreciate your business and are dedicated to providing you with a roof that offers protection and peace of mind for years to come. If you have any questions regarding the warranty or maintenance packages, please do not hesitate to contact us.

**Save Signature!**

<https://valleywidepro.com> [billing@valleywidepro.com](mailto:billing@valleywidepro.com)



**Updated**

April 15, 2025 @ 12:02 am

Estimate updated by valleywide.



**Viewed**

April 15, 2025 @ 12:04 am

Estimate viewed by for the first time.

-  **Viewed**  
April 15, 2025 @ 6:50 am  
Estimate viewed by 172.70.210.229 for the first time.
-  **Viewed**  
April 15, 2025 @ 6:51 am  
Estimate viewed by 162.158.186.192 for the first time.
-  **Viewed**  
April 15, 2025 @ 6:52 am  
Estimate viewed by 172.70.215.86 for the first time.
-  **Viewed**  
April 15, 2025 @ 6:53 am  
Estimate viewed by 162.158.90.210 for the first time.
-  **Viewed**  
April 15, 2025 @ 6:53 am  
Estimate viewed by 172.71.167.183 for the first time.
-  **Viewed**  
April 15, 2025 @ 6:53 am  
Estimate viewed by 172.70.207.167 for the first time.
-  **Viewed**  
April 15, 2025 @ 6:53 am  
Estimate viewed by 172.70.206.14 for the first time.
-  **Viewed**  
April 15, 2025 @ 7:09 am  
Estimate viewed by 172.70.179.45 for the first time.
-  **Viewed**  
April 15, 2025 @ 2:18 pm  
Estimate viewed by 172.69.33.186 for the first time.
-  **Viewed**  
April 15, 2025 @ 9:39 pm  
Estimate viewed by 162.158.41.186 for the first time.
-  **Viewed**  
April 15, 2025 @ 9:39 pm  
Estimate viewed by 172.68.26.186 for the first time.
-  **Viewed**  
April 15, 2025 @ 11:11 pm  
Estimate viewed by 172.70.210.132 for the first time.

 Viewed

April 15, 2025 @ 11:11 pm

Estimate viewed by 172.70.127.128 for the first time.

 Viewed

April 15, 2025 @ 11:11 pm

Estimate viewed by 172.71.255.96 for the first time.

 Viewed

April 18, 2025 @ 1:13 am

Estimate viewed by (valleywide) for the first time.

 Viewed

April 18, 2025 @ 11:31 am

Estimate viewed by 198.41.227.182 for the first time.

 Viewed

April 18, 2025 @ 11:32 am

Estimate viewed by 198.41.227.123 for the first time.

 Viewed

April 18, 2025 @ 11:32 am

Estimate viewed by 172.69.6.27 for the first time.

 Viewed

April 18, 2025 @ 11:32 am

Estimate viewed by 198.41.227.9 for the first time.

 Viewed

April 18, 2025 @ 11:33 am

Estimate viewed by 198.41.227.90 for the first time.

 Viewed

April 18, 2025 @ 11:35 am

Estimate viewed by 198.41.227.142 for the first time.

 Viewed

April 18, 2025 @ 11:39 am

Estimate viewed by 198.41.227.18 for the first time.

 Viewed

April 18, 2025 @ 11:48 am

Estimate viewed by 172.69.33.187 for the first time.

 Viewed

April 21, 2025 @ 1:40 pm

Estimate viewed by 172.70.214.152 for the first time.

 **Viewed**  
April 21, 2025 @ 10:28 pm

Estimate viewed by 172.71.166.69 for the first time.

 **Viewed**  
April 28, 2025 @ 6:16 pm

Estimate viewed by 172.70.210.133 for the first time.

 **Viewed**  
April 29, 2025 @ 3:52 pm

Estimate viewed by 162.158.90.82 for the first time.

 **Viewed**  
May 1, 2025 @ 10:27 am

Estimate viewed by 172.69.34.139 for the first time.

 **Viewed**  
May 10, 2025 @ 6:22 am

Estimate viewed by 104.23.195.103 for the first time.

 **Viewed**  
May 29, 2025 @ 12:26 pm

Estimate viewed by 172.71.194.56 for the first time.

 **Viewed**  
May 29, 2025 @ 12:26 pm

Estimate viewed by 172.70.43.209 for the first time.

 **Viewed**  
May 29, 2025 @ 12:26 pm

Estimate viewed by 162.158.159.74 for the first time.

 **Viewed**  
May 31, 2025 @ 6:26 pm

Estimate viewed by 172.71.254.18 for the first time.

 **Viewed**  
June 3, 2025 @ 12:04 pm

Estimate viewed by 172.71.166.248 for the first time.

 **Viewed**  
June 3, 2025 @ 12:10 pm

Estimate viewed by 172.69.65.227 for the first time.

 **Viewed**  
June 3, 2025 @ 1:55 pm

Estimate viewed by 172.71.255.61 for the first time.

 Viewed

June 4, 2025 @ 9:22 am

Estimate viewed by 172.70.127.104 for the first time.

 Viewed

June 5, 2025 @ 1:16 am

Estimate viewed by 172.71.254.123 for the first time.

 Viewed

June 5, 2025 @ 3:12 am

Estimate viewed by 108.162.216.121 for the first time.

 Viewed

July 4, 2025 @ 10:45 pm

Estimate viewed by 162.158.189.98 for the first time.

 Viewed

August 17, 2025 @ 9:14 pm

Estimate viewed by 172.69.74.219 for the first time.

 Viewed

August 18, 2025 @ 7:52 am

Estimate viewed by 172.68.7.38 for the first time.

 Viewed

August 19, 2025 @ 5:48 am

Estimate viewed by 104.23.195.57 for the first time.

 Viewed

August 19, 2025 @ 5:58 am

Estimate viewed by 104.23.195.80 for the first time.

 Viewed

August 19, 2025 @ 6:01 am

Estimate viewed by 104.23.195.81 for the first time.

 Viewed

August 19, 2025 @ 6:02 am

Estimate viewed by 104.23.195.22 for the first time.

 Viewed

August 19, 2025 @ 6:02 am

Estimate viewed by 104.23.195.102 for the first time.

 Viewed

August 19, 2025 @ 6:03 am

Estimate viewed by 172.69.74.234 for the first time.

 Viewed

August 19, 2025 @ 6:04 am

Estimate viewed by 172.69.74.253 for the first time.

 Viewed

August 19, 2025 @ 9:47 am

Estimate viewed by 141.101.99.153 for the first time.

 Viewed

August 19, 2025 @ 1:45 pm

Estimate viewed by 141.101.99.112 for the first time.

 Viewed

August 20, 2025 @ 7:33 am

Estimate viewed by 172.71.160.122 for the first time.

 Viewed

August 22, 2025 @ 1:34 pm

Estimate viewed by 141.101.95.100 for the first time.

 Viewed

September 10, 2025 @ 7:57 am

Estimate viewed by 172.69.17.66 for the first time.

 Viewed

September 10, 2025 @ 10:36 am

Estimate viewed by 172.69.17.67 for the first time.

 Viewed

September 12, 2025 @ 2:52 am

Estimate viewed by 172.69.59.31 for the first time.

 Viewed

September 18, 2025 @ 9:44 pm

Estimate viewed by 172.71.254.131 for the first time.

 Updated

October 24, 2025 @ 12:46 pm

Estimate updated by valleywide.

 Viewed

October 30, 2025 @ 2:20 am

Estimate viewed by 172.70.126.106 for the first time.

 Viewed

December 5, 2025 @ 2:12 pm

Estimate viewed by 172.70.208.132 for the first time.

 Viewed

December 17, 2025 @ 4:43 am

Estimate viewed by 172.70.38.138 for the first time.

 Viewed

December 18, 2025 @ 2:59 am

Estimate viewed by 172.70.100.100 for the first time.

 Viewed

December 20, 2025 @ 5:46 am

Estimate viewed by 172.70.134.114 for the first time.

 Viewed

February 3, 2026 @ 3:51 pm

Estimate viewed by 104.23.213.81 for the first time.

 Viewed

February 6, 2026 @ 3:10 am

Estimate viewed by 172.71.148.37 for the first time.

 Viewed

March 6, 2026 @ 12:49 am

Estimate viewed by 172.71.255.2 for the first time.

 Viewed

March 6, 2026 @ 7:07 am

Estimate viewed by 104.22.66.89 for the first time.

 Viewed

March 6, 2026 @ 10:47 am

Estimate viewed by 172.69.59.155 for the first time.

 Viewed

March 15, 2026 @ 8:13 am

Estimate viewed by 172.68.26.223 for the first time.

 Viewed

March 25, 2026 @ 1:07 am

Estimate viewed by 162.158.107.11 for the first time.

 Viewed

March 26, 2026 @ 6:05 pm

Estimate viewed by 104.22.62.107 for the first time.

 Viewed

April 25, 2026 @ 4:26 am

Estimate viewed by 104.22.17.145 for the first time.

 Viewed

May 24, 2026 @ 4:41 pm

Estimate viewed by 172.71.1.146 for the first time.



 Viewed

June 19, 2026 @ 9:22 am

Estimate viewed by 172.69.7.139 for the first time.

